



533...B11  
593...C11  
594...D11  
594...E11  
594...F11  
595...G11  
596...H11  
597...I11  
598...J11  
598...K11  
622...L11  
639...M11  
643...N11  
644...O11

810ER

## ASSEMBLY IDENTIFICATION REPORT, COPYRIGHTED 1992 BY THE TIMKEN COMPANY

593 MAY 6, 1992 05.18-

PAGE 141

ASSEMBLY  
PART NUMBER

	COMPONENT PART NUMBER	COMPONENT DESC	SP TY	COMP INSP	Q/A SGC	COMP ASSY CODE	ASSY INSP	ASSY SGC DESC	END PLATE OR PRELOAD	DISCONTINUE DATE
	593A	CONE		40024	2 2EF	90264	40024	5CA ASSEMBLY	EP .0120	
	592A	CUP		40024	2 1CE					
	Y4S 592A	CUP SPCR Q	Q	20000	1 04R					
	593A	CONE		0	1 2EF	90158	0	6CA ASSEMBLY		
	592-B	CUP		0	1 1CH					
	593A	CONE		0	2 2EF	90031	0	6CB ASSEMBLY		
	592D	CUP		0	1 1CG					
	X15-593	CONE SPCR A	A	30000	1 04Q	903A1	30000	6CB ASSEMBLY	PL .0010	
	593A	CONE		40024	2 2EF	90178	40024	5CB ASSEMBLY	EP .0120	
	592D	CUP		40024	1 1CB					
	X15-593	CONE SPCR A	A	20000	1 04Q					
	593A	CONE		40024	2 2EF	90306	40024	5CB ASSEMBLY	EP .0120	
	592D	CUP		40024	1 1CB					
	X25-593	CONE SPCR A	A	20000	1 04B					
	593A	CONE		0	2 2EF	90290	0	6CB ASSEMBLY		
	592DC	CUP		0	1 1CG					
	593A	CONE		40024	2 2EF	90249	40024	5CB ASSEMBLY	EP .0100	
	592DC	CUP		40024	1 1CB					
	X15-593	CONE SPCR A	A	20000	1 04Q					
	593A	CONE		0	2 2EF	90283	0	6CB ASSEMBLY	EP .0050	
	592DC	CUP		0	1 1CG					
	X15-593	CONE SPCR A	A	0	1 04Q					
593-B	593-B	CONE		00	1 2EF	90032	00	7CA ASSEMBLY		
	592A	CUP		00	1 1CF					
	593-B	CONE		00	1 2EF	90118	00	7CA ASSEMBLY		
	592-B	CUP		00	1 1CH					
593-S	593-S	CONE		0	1 2EF	90285	0	6CA ASSEMBLY		
	592A	CUP		0	1 1CF					
	593-S	CONE		0-174	1 2EF	90238	0-174	6CA ASSEMBLY		
	592A	CUP		0	1 1CF					
	593-S	CONE		40024	2 2EA	90230	40024	5CA ASSEMBLY	EP .0220	
	592A	CUP		40024	2 1CE					
	Y9S-592A	CUP SPCR RSR	R	20000	1 04C					
	X15-593-S	CONE SPCR A	A	20000	1 04B					
	593-S	CONE		40024	2 2EA	90253	40024	5CA ASSEMBLY	EP .0220	
	592A	CUP		40024	2 1CE					
	X35-593-S	CONE SPCR A	A	20000	1 04B					
	593-S	CONE		45024	2 2EA	95253	45024	5CA ASSEMBLY	EP .0220	
	592A	CUP		40024	2 1CE					
	X35-593-S	CONE SPCR A	A	20000	1 04B					
	593-S	CONE		30000	2 2EF	90271	30000	6CB ASSEMBLY	EP .0030	
	592D	CUP		30000	1 1CG	90247	30000	6CB ASSEMBLY	EP .0050	
	X25-593-S	CONE SPCR A	A	0	1 04B					
	593-S	CONE		40024	2 2EA	90259	40024	5CB ASSEMBLY	EP .0120	
	592D	CUP		40024	1 1CB					
	X25-593-S	CONE SPCR A	A	20000	1 04B					
NA593	NA593	CONE		20194	2 2EA	90035	20194	5CB ASSEMBLY	EP .0210	
	592D	CUP		20081	1 1CB					
	NA593	CONE		20199	2 2EA	90036	20199	5CB ASSEMBLY	EP .0160	
	592D	CUP		20081	1 1CB					

810ER	ASSEMBLY IDENTIFICATION REPORT, COPYRIGHTED 1992 BY THE TIMKEN COMPANY								593	MAY 6, 1992	05.18-	PAGE	142
ASSEMBLY PART NUMBER	COMPONENT PART NUMBER	DESC	SP TY	COMP INSP	Q-A SGC	COMP CODE	ASSY INSP	ASSY SGC DESC	END PLAY OR PRELOAD	OBSCLETE DATE			
	NA593 592D	CONE CUP		30000 30001	2 2EF 1 ICG	90033	30000	6CB ASSEMBLY	EP .0040				
	NA593 592D	CONE CUP		30142 30001	2 2EF 1 ICG	90034	30142	6CB ASSEMBLY	EP .0000				
NA593-SH	NA593-SH 592D Y35-592A	CONE CUP		20199 20081 20000	4 2EA 2 1CB 1 04C	90037	20199	5CC ASSEMBLY	EP .0160				
594	594 592	CONE CUP	0	0	1 2EF 1 ICF	90038	0	6CA ASSEMBLY					
	594 592A	CONE CUP	0	0	1 2EF 1 ICF	90039	0	6CA ASSEMBLY					
	594 592A	CONE CUP	0-30	0	1 2EF 1 ICF	90214	0-30	6CA ASSEMBLY					
	594 592A	CONE CUP	0-30	0-39	1 2EF 1 ICF	90126	0-33	6CA ASSEMBLY					
	594 592A	CONE CUP	00	00	1 2EF 1 ICF	906B2	00	7CA ASSEMBLY					
	594 Y35-592A	CONE CUP SPCR R	40024 20000	2 2EP 1 04C	88192	40024	5CA ASSEMBLY	EP :8120					
	594 592A Y45-592A	CONE CUP	20024 20024 20000	2 2EP 2 1CE 1 04R	90219	20024	5CA ASSEMBLY	EP .0080					
	594 592A Y45-592A	CONE CUP	40024 40024 20000	2 2EP 2 1CE 1 04R	90154	40024	5CA ASSEMBLY	EP .0100					
	594 592A X45-594	CONE CUP	20157 20024 20000	2 2EP 2 1CE 1 04Q	90269 90248	20214	5CA ASSEMBLY	EP :0030					
	594 592A X45-594	CONE CUP	40024 40024 20000	2 2EP 2 1CE 1 04Q	90040	40024	5CA ASSEMBLY	EP .0080					
	594 592-B	CONE CUP	30580 30000	1 2EF 1 ICH	903J3	30580	6CA ASSEMBLY						
	594 592-B	CONE CUP	0	0	1 2EF 1 ICH	90041	0	6CA ASSEMBLY		73 073			
	594 592-B	CONE CUP	0-30	0	1 2EF 1 ICH	90218	0 30	6CA ASSEMBLY					
	594 592-B	CONE CUP	0-32	0-32	1 2EF 1 ICH	90042	0-32	6CA ASSEMBLY					
	594 592-B	CONE CUP	0-580	0	1 2EF 1 ICH	90312	0 580	6CA ASSEMBLY					
	594 592D	CONE CUP	0	0	2 2EF 1 ICG	90115	0	6CB ASSEMBLY					
	594 592D Y35-592A X25-594	CONE CUP	20024 20024 20000 20000	4 2EP 2 1CB 1 04C 2 04Q	90252	20024	5CC ASSEMBLY	EP .0120					

810ER

## ASSEMBLY IDENTIFICATION REPORT, COPYRIGHTED 1992 BY THE TIMKEN COMPANY

594 MAY 6, 1992 05.18-

PAGE 143

ASSEMBLY  
PART NUMBER

COMPONENT PART NUMBER	COMPONENT PART NUMBER	SP DESC	TY INSP	COMP Q/A	COMP SGC	ASSY CODE	ASSY INSP	ASSY SGC	ASSY DESC	END PLAY OR PRELOAD	OBSOLETE DATE
594	CONE	40024	4	2EP	90131	40024	5CB ASSEMBLY	EP .0150			
592D	CUP	40024	2	1CB							
X3S-592A	CUP SPCR R	20000	1	04C							
X3S-594	CONE SPCR A1	20000	2	04B							
594	CONE	2E024	2	2EA	9E2A7	2E024	5CB ASSEMBLY	EP .0030			
592D	CUP	2E024	1	1CB							
X2S-594	CONE SPCR A	2E000	1	04Q							
594	CONE	20024	2	2EP	9E2A3	2E024	5CB ASSEMBLY	EP .0120			
592D	CUP	20024	1	1CB							
X2S-594	CONE SPCR A	20000	1	04Q							
594	CONE	20024	2	2EP	90127	20024	5CB ASSEMBLY	EP .0030			
592D	CUP	20024	1	1CB	90152	20024	5CB ASSEMBLY	EP .0060			
X2S-594	CONE SPCR A	20000	1	04Q	902A4	20024	5CB ASSEMBLY	EP .0080			
					90044	20024	5CB ASSEMBLY	EP .0100			
					90207	20024	5CB ASSEMBLY	EP .0120			
					90045	20024	5CB ASSEMBLY	EP .0140			
					90184	20024	5CB ASSEMBLY	EP .0160			
594	CONE	20024	2	2EP	902A9	20649	5CB ASSEMBLY				
592D	CUP	20024	1	1CB							
X2S-594	CONE SPCR A	40000	1	04Q							
594	CONE	20157	2	2EP	90046	20214	5CB ASSEMBLY	EP .0060			
592D	CUP	20157	1	1CB							
X2S-594	CONE SPCR A	20000	1	04Q							
594	CONE	20157	2	2EP	90268	20157	5CB ASSEMBLY	EP .0060			
592D	CUP	20157	1	1CB							
X2S-594	CONE SPCR A	20000	1	04Q							
594	CONE	30000	2	2EF	90109	30000	6CB ASSEMBLY	EP .0040			
592D	CUP	30000	1	1CG	90193	30000	6CB ASSEMBLY	EP .0050			
X2S-594	CONE SPCR A	0	1	04Q	903A8	30000	6CB ASSEMBLY	EP .0060			
594	CONE	30030	2	2EF	90043	30030	6CB ASSEMBLY	EP .0030			
592D	CUP	30000	1	1CG	90153	30030	6CB ASSEMBLY	EP .0040			
X2S-594	CONE SPCR A	0	1	04Q							
594	CONE	30434	2	2EF	903B3	30434	6CB ASSEMBLY	EP .0010			
592D	CUP	30039	1	1CG	90311	30434	6CB ASSEMBLY	EP .0030			
X2S-594	CONE SPCR A	0	1	04Q							
594	CONE	4E024	2	2EP	9E4A5	4E024	5CB ASSEMBLY	EP .0120			
592D	CUP	4E024	1	1CB							
X2S-594	CONE SPCR A	2E000	1	04Q							
594	CONE	40024	2	2EP	90048	40024	5CB ASSEMBLY	EP .0080			
592D	CUP	40024	1	1CB	90170	40024	5CB ASSEMBLY	EP .0100			
X2S-594	CONE SPCR A	20000	1	04Q	90049	40024	5CB ASSEMBLY	EP .0120			
					90235	40024	5CB ASSEMBLY	EP .0160			
					90050	40024	5CB ASSEMBLY	EP .0200			
594	CONE	40024	2	2EP	904A1	40499	5CB ASSEMBLY				
592D	CUP	40024	1	1CB							
X2S-594	CONE SPCR A	40000	1	04Q							
594	CONE	20024	2	2EP	90146	20024	5CB ASSEMBLY	EP .0110			
592D	CUP	20024	1	1CB							
X3S-594	CONE SPCR A1	20000	1	04B							
594	CONE	40024	2	2EP	90255	40024	5CB ASSEMBLY	EP .0120			
592D	CUP	40024	1	1CB							
X3S-594	CONE SPCR A1	20000	1	04B							
594	CONE	20024	2	2EP	90203	20024	5CB ASSEMBLY	EP .0120			
592DC	CUP	20024	1	1CB							
X2S-594	CONE SPCR A	20000	1	04Q							

ASSEMBLY IDENTIFICATION REPORT, COPYRIGHTED 1992 BY THE TIMKEN COMPANY										594	MAY	6x.1992	05.18-	PAGE	144	
810ER	ASSEMBLY PART NUMBER	COMPONENT PART NUMBER	DESC	SP TY	COMP INSP	Q/A SGC	ASSY CODE	ASSY INSP	ASSY SGC DESC	END PLAY OR PRELOAD	OBSOLETE DATE					
	594 592DC X2S-594	CONE CUP CONE SPCR A		30000 30000 0	2 2EF 1 1CG 1 04Q	90185 90226 90165	30000 30030 3003Q	6CB ASSEMBLY 6CB ASSEMBLY 6CB ASSEMBLY	EP .0040 EP .0000 EP .0030							
	594 592DC X2S-594	CONE CUP CONE SPCR A		30030 30000 0	2 2EF 1 1CG 1 04Q	90226 90165 90206	30030 3003Q 40024	5CB ASSEMBLY 5CB ASSEMBLY 5CB ASSEMBLY	EP .0100 EP .0120 EP .0120							
	594 592DC X2S-594	CONE CUP CONE SPCR A		40024 40024 20000	2 2EP 1 1CB 1 04Q	90162 90206 90215	40024 40024 0	5CB ASSEMBLY 5CB ASSEMBLY 6CB ASSEMBLY	EP .0040 EP .0040 EP .0040							
	594 592XE X2S-594	CONE CUP CONE SPCR A		0 0 0	2 2EF 1 1CF 1 04Q	90215 90300 90243	0 0 30000	6CB ASSEMBLY 6CA ASSEMBLY 6CA ASSEMBLY	EP .0060 EP .0060 EP .0060							
	594 592XE Y15-592XE X6S-594	CONE CUP CUP SPCR R CONE SPCR A		30000 30000 0 0	2 2EF 2 1CF 1 04C 1 04B	90243 90292 90292 90292	0 0 0 0	6CA ASSEMBLY 6CA ASSEMBLY 6CA ASSEMBLY 6CA ASSEMBLY	EP .0060 EP .0060 EP .0060 EP .0060							
	594 592XS	CONE CUP		0 0	1 2EF 1 1CF	90292	0	6CA ASSEMBLY								
	594 592XS Y15-592XS	CONE CUP CUP SPCR S		40024 40024 20000	2 2EP 2 1CA 1 04R	90201	40024	5CA ASSEMBLY	EP .0060							
	594 593X	CONE CUP		0 0	1 2EF 1 1CF	90273	0	6CA ASSEMBLY								
594A	594A 592A	CONE CUP		0 0	1 2EF 1 1CF	90133	0	6CA ASSEMBLY								
	594A 592-B	CONE CUP		0 0	1 2EF 1 1CH	90134	0	6CA ASSEMBLY								
	594A 592D	CONE CUP		0 0	2 2EF 1 1CG	90159	0	6CB ASSEMBLY								
	594A 592D X2S-594	CONE CUP CONE SPCR A		20024 20024 20000	2 2EP 1 1CB 1 04Q	90233 902B2 902B2	20024 20024 20024	5CB ASSEMBLY 5CB ASSEMBLY 5CB ASSEMBLY	EP .0080 EP .0120 EP .0120							
	594A 592D X2S-594	CONE CUP CONE SPCR A		20024 20024 40000	2 2EP 1 1CB 1 04Q	902B1	20649	5CB ASSEMBLY								
	594A 592D X2S-594	CONE CUP CONE SPCR A		30434 30039 0	2 2EF 1 1CG 1 04Q	903A2	30434	6CB ASSEMBLY	EP .0000							
	594A 592D X2S-594	CONE CUP CONE SPCR A		4E024 4E024 2E000	2 2EA 1 1CB 1 04Q	9E4A6	4E024	5CB ASSEMBLY								
	594A 592D X2S-594	CONE CUP CONE SPCR A		40024 40024 20000	2 2EP 1 1CB 1 04Q	90137 90140 90161	40024 40024 0	5CB ASSEMBLY 5CB ASSEMBLY 6CB ASSEMBLY	EP .0080 EP .0120 EP .0120							
	594A 592DC	CONE CUP		0 0	2 2EF 1 1CG	90161	0	6CB ASSEMBLY								
	594A 592DC X2S-594	CONE CUP CONE SPCR A		40024 40024 20000	2 2EP 1 1CB 1 04Q	90309 90194 90194	40024 40024 40024	5CB ASSEMBLY 5CB ASSEMBLY 5CB ASSEMBLY	EP .0120 EP .0160 EP .0160							

ASSEMBLY IDENTIFICATION REPORT, COPYRIGHTED 1992 BY THE TIMKEN COMPANY										594	MAY 6, 1992	05.18-	PAGE
ASSEMBLY PART NUMBER	COMPONENT PART NUMBER	COMPONENT DESC	SP TY	COMP INSP	Q/A SGC	COMP ASSY CODE	ASSY INSP	ASSY SGC	ASSY DESC	END PLAY OR PRELOAD	Obsolete DATE		
	594A	CONE		20157	2	2EP	90296	20157	5CA ASSEMBLY	EP .0050	78_115		
	592XE	CUP		20157	2	1CA							
X15-592XE	CUP SPCR			20000	1	04C							
X15-594A	CONE SPCR A1			20000	1	04B							
594-B	594-B	CONE	00		1	2EF	90104	00	7CA ASSEMBLY		91 298		
	592A	CUP	00		1	1CF							
	594-B	CONE	00		1	2EF	90121	00	7CA ASSEMBLY				
	592-B	CUP	00		1	1CH							
	594-B	CONE	00		1	2EF	90242	00	7CB ASSEMBLY				
	592DC	CUP	00		1	1CG							
594H	594H	CONE	0		1	2EF	90052	0	6CA ASSEMBLY				
	592A	CUP	0		1	1CF							
	594H	CONE	0		1	2EF	90053	0	6CA ASSEMBLY				
	592-B	CUP	0		1	1CH							
595	595	CONE	0		1	2EF	90054	0	6CA ASSEMBLY				
	592	CUP	0		1	1CF							
	595	CONE	0		1	2EF	90179	0	6CA ASSEMBLY				
	592A	CUP	0		1	1CF							
	595	CONE	00		1	2EF	90304	00	7CA ASSEMBLY				
	592A	CUP	00		1	1CF							
	595	CONE	0		1	2EF	90055	0	6CA ASSEMBLY				
	592-B	CUP	0		1	1CH							
	595	CONE	0		2	2EF	90056	0	6CB ASSEMBLY				
	592D	CUP	0		1	1CG							
	595	CONE	0-30		2	2EF	90167	0-33	6CB ASSEMBLY				
	592D	CUP	0-39		1	1CG							
	595	CONE	20024		2	2EA	90156	20024	5CB ASSEMBLY	EP .0040			
X15-595	592D	CUP	20024		1	1CB	90267	20024	5CB ASSEMBLY	EP .0060			
X15-595	CONE SPCR A		20000		1	04Q	90059	20024	5CB ASSEMBLY	EP .0080			
							90060	20024	5CB ASSEMBLY	EP .0100			
							90211	20024	5CB ASSEMBLY	EP .0120			
	595	CONE	30000		2	2EF	90141	30000	6CB ASSEMBLY	EP .0020			
X15-595	592D	CUP	30000		1	1CG	90163	30000	6CB ASSEMBLY	EP .0030			
X15-595	CONE SPCR A		0		1	04Q	90057	30000	6CB ASSEMBLY	EP .0040			
							90058	30000	6CB ASSEMBLY	EP .0050			
	595	CONE	40024		2	2EA	90129	40024	5CB ASSEMBLY	EP .0080			
X15-595	592D	CUP	40024		1	1CB	90256	40024	5CB ASSEMBLY	EP .0100			
X15-595	CONE SPCR A		20000		1	04Q	90061	40024	5CB ASSEMBLY	EP .0120			
							90100	40024	5CB ASSEMBLY	EP .0200			
	595	CONE	0		2	2EF	90102	0	6CB ASSEMBLY	EP .0920			
X15-595	592D	CUP	0		1	1CG							
X15-595	CONE SPCR A		0		1	04Q							
	595	CONE	20024		2	2EA	902A1	20024	5CB ASSEMBLY	EP .0120			
X25-595	592D	CUP	20024		1	1CB							
X25-595	CONE SPCR A1		20000		1	04B							
	595	CONE	40024		2	2EA	90299	40024	5CB ASSEMBLY	EP .0120			
X25-595	592D	CUP	40024		1	1CB	90192	40024	5CB ASSEMBLY	EP .0160			
X25-595	CONE SPCR A1		20000		1	04B							
	595	CONE	20024		2	2EA	90263	20024	5CB ASSEMBLY	EP .0080			
X15-595	592DC	CUP	20024		1	1CB							
X15-595	CONE SPCR A		20000		1	04Q							

ASSEMBLY IDENTIFICATION REPORT, COPYRIGHTED 1992 BY THE TIMKEN COMPANY											595	MAY	6, 1992	05.18-	PAGE
810ER	ASSEMBLY PART NUMBER	COMPONENT PART NUMBER	DESC	SP TY	COMP INSP	A/A	COMP SGC	ASSY CODE	ASSY INSP	ASSY SGC	END PLAY PRELOAD	OR	OBSOLETE DATE		
595A	595 592DC X1S-595	CONE CUP CONE SPCR A		40024 40024 20000	2 1 1	2EA 1CB 04Q	90266 90293 90024	40024	5CB ASSEMBLY 5CB ASSEMBLY	EP .0080 EP .0120					
	595A 592A	CONE CUP		0	1	2EF 1CF	90062	0	6CA ASSEMBLY						
	595A 592-B	CONE CUP		0	1	2EF 1CH	90277	0	6CA ASSEMBLY						
	595A 592D	CONE CUP		0	2	2EF 1CG	90063	0	6CB ASSEMBLY						
	595A 592D X1S-595A	CONE CUP CONE SPCR A		30000 30000 20000	2 1 1	2EF 1CG 04Q	90240	30000	6CB ASSEMBLY	EP .0040					
	595A 592D X1S-595A	CONE CUP CONE SPCR A		40024 40024 20000	2 1 1	2EA 1CB 04Q	90260	40024	5CB ASSEMBLY	EP .0120					
	595A 592D X1S-595A	CONE CUP CONE SPCR A		0	2	2EF 1CG 04Q	90180	0	6CB ASSEMBLY	EP .0040					
	595A 592DC X1S-595A	CONE CUP CONE SPCR A		40024 40024 20000	2 1 1	2EF 1CG 04Q	90305	40024	5CB ASSEMBLY	EP .0120					
	595A 592DC X1S-595A	CONE CUP CONE SPCR A		0	2	2EF 1CG 04Q	90213	0	6CB ASSEMBLY	EP .0030					
	596	CONE CUP		0	1	2EF 1CF	90106	0	6CA ASSEMBLY						
596	596 592A	CONE CUP		0	1	2EF 1CF	90064	0	6CA ASSEMBLY						
	596 592-B	CONE CUP		0	1	2EF 1CH	90302	0	6CA ASSEMBLY						
	596 592D	CONE CUP		0	2	2EF 1CG	90139	0	6CB ASSEMBLY						
	596 592D X1S-596	CONE CUP CONE SPCR A		20157 20024 20000	2 1 1	2EL 1CB 04B	90216	20214	5CB ASSEMBLY	EP .0020					
	596 592D X1S-596	CONE CUP CONE SPCR A		30000 30000 0	2 1 1	2EF 1CG 04B	90257 90166 90245 90065 90294 90066	30000 30000 30000 30000 30000 30000	6CB ASSEMBLY 6CB ASSEMBLY 6CB ASSEMBLY 6CB ASSEMBLY 6CB ASSEMBLY 6CB ASSEMBLY	EP .0010 EP .0020 EP .0040 EP .0050 EP .0060 EP .0120					
	596 592D X1S-596	CONE CUP CONE SPCR A		40024 40024 20000	2 1 1	2EL 1CB 04B	90198 90067 90117 90279	40024 40024 40024 40024	5CB ASSEMBLY 5CB ASSEMBLY 5CB ASSEMBLY 5CB ASSEMBLY	EP .0060 EP .0080 EP .0120 EP .0160					
	596 592D X1S-596	CONE CUP CONE SPCR A		0	2	2EF 1CG 04B	90138	0	6CB ASSEMBLY	EP .0050					
	596 592D X1S-596	CONE CUP CONE SPCR		40024 40024 20000	2 1 1	2EL 1CB 04B	90284	40024	5CB ASSEMBLY	EP .0120	78 110				

B10ER	ASSEMBLY IDENTIFICATION REPORT, COPYRIGHTED 1992 BY THE TIMKEN COMPANY										596	MAY 6, 1992	05.18-	PAGE	147
ASSEMBLY PART NUMBER	COMPONENT PART NUMBER	DESC	SP TY	COMP INSP	Q/A	COMP SGC	ASSY CODE	ASSY INSP	ASSY SGC	ASSY DESG	END PLAY OR PRELOAD	OBSCOLETE DATE			
	596 592DC X1S-596	CONE CUP CONE SPCR A		40024 40024 20000	2 1 1	2EL ICB 04B	90250 90157 40024	40024 40024 5CB ASSEMBLY	5CB ASSEMBLY		EP .0120 EP .0160				
596-S	596-S 592A	CONE CUP		0	1	2EF	90224	0	6CA ASSEMBLY						
	596-S 592-B	CONE CUP		0	1	2EF	90301	0	6CA ASSEMBLY						
	596-S 592D X2S-596	CONE CUP CONE SPCR A		20024 20024 20000	2 1 1	2EA ICB 04B	90068 90069 20024	20024 20024 5CB ASSEMBLY	5CB ASSEMBLY		EP .0080 EP .0120				
	596-S 592D X2S-596	CONE CUP CONE SPCR A		40024 40024 20000	2 1 1	2EA ICB 04B	90070 90234 40024	40024 5CB ASSEMBLY	5CB ASSEMBLY		EP .0080 EP .0120				
	596-S 592DC X2S-596	CONE CUP CONE SPCR A		40024 40024 20000	2 1 1	2EA ICB 04B	90272	40024	5CB ASSEMBLY		EP .0120				
596W	596W 592A	CONE CUP		0	1	2EF	90278	0	6CA ASSEMBLY						
NA596-SH	K87718 K93892	CONE CLOSURE		20024 20001	2 1	2EF ICF	90171	20000	SFD ASSEMBLY		EP .0000-.0050				
	NA596-SH K93891 K93892	CONE CUP CLOSURE		20024 20001	2 1	2EA IFK	90124	20000	SFD ASSEMBLY		EP .0000-.0050				
	NA596-SH K93891 K93892	CONE CUP CLOSURE		20024 20411	2 1	2EA IFK	90217	20411	SFD ASSEMBLY		EP .0000-.0050 76 049				
	NA596-SH K101989 K93892	CONE CUP CLOSURE		20024 20001	2 1	2EA IFK	90177	20000	SED ASSEMBLY		EP .0000-.0050				
	NA596-SH K106815 K93892	CONE CUP CLOSURE		20024 20001	2 1	2EA IFK	90210	20000	SFD ASSEMBLY		EP .0000-.0050				
	NA596-SH K426877 K93892	CONE CUP CLOSURE		20000 20001	2 1	2EA IHB	90279	20000	SHB ASSEMBLY		EP .0000-.0050 74 077				
	NA596-SH K516773 K93892	CONE CUP CLOSURE		20024 20229	2 1	2EA IEK	90300	20229	SED ASSEMBLY		EP .0000-.0050				
597	597 592	CONE CUP	0	0	1	2EF	90071	0	6CA ASSEMBLY						
	597 592A	CONE CUP	0	0	1	2EF	90072	0	6CA ASSEMBLY						
	597 592A	CONE CUP	0-30	0	1	2EF	90073	0-30	6CA ASSEMBLY						
	597 592A	CONE CUP	0-30	0-39	1	2EF	90303	0-33	6CA						
	597 592-B	CONE CUP	0	0	1	2EF	90074	0	6CA ASSEMBLY						
	597 592D	CONE CUP	0	0	2	2EF	90105	0	6CB ASSEMBLY						

ASSEMBLY IDENTIFICATION REPORT, COPYRIGHTED 1992 BY THE TIMKEN COMPANY											597	MAY	6, 1992	05.18-	PAGE	148
ASSEMBLY PART NUMBER	COMPONENT PART NUMBER	DESC	SP TY	COMP INSP	Q/A	COMP SGC	ASSY CODE	ASSY INSP	ASSY SGC	ASSY DESC	END PLAY OR PRELOAD	OBSOLETE DATE				
	597 592D X15-597	CONE CUP CONE SPCR A		30000 30000 0		2 2EF 1 1CG 1 04B	90110	30000	6CB ASSEMBLY	EP .0040						
	597 592D X15-597	CONE CUP CONE SPCR A		40024 40024 20000		2 2EA 1 1CB 1 04B	90220	40024	5CB ASSEMBLY	EP .0120						
	597 592D X15-597	CONE CUP CONE SPCR A		0 0 0		2 2EF 1 1CG 1 04B	90075	0	6CB ASSEMBLY	EP .0040						
	597 592DC X15-597	CONE CUP CONE SPCR A		40024 40024 20000		2 2EA 1 1CB 1 04B	90222	40024	5CB ASSEMBLY	EP .0080						
	597 592XS	CONE CUP		0 0		1 2EF 1 1CF	90291	0	6CA ASSEMBLY							
	597 593X	CONE CUP		0 0		1 2EF 1 1CF	90199	0	6CA ASSEMBLY							
597-B	597-B 592A	CONE CUP		00 00		1 2EF 1 1CF	90231	00	7CA ASSEMBLY		90 135					
	597-B 592-B	CONE		00		1 2EF	90241	00	7CA ASSEMBLY		90 135					
598	598 592	CONE CUP		0 0		1 2EF 1 1CF	90076	0	6CA ASSEMBLY							
	598 592	CONE CUP		0-580 0		1 2EF 1 1CF	90307	0-580	6CA ASSEMBLY							
	598 592	CONE CUP		00 00		1 2EF 1 1CF	90306	00	7CA ASSEMBLY							
	598 592A	CONE CUP		0 0		1 2EF 1 1CF	90077	0	6CA ASSEMBLY							
	598 592A	CONE CUP		0-30 0-39		1 2EF 1 1CF	90119	0-33	6CA ASSEMBLY							
	598 592A	CONE CUP		0-174 0		1 2EF 1 1CF	90239	0-174	6CA ASSEMBLY							
	598 592A	CONE CUP		00 00		1 2EF 1 1CF	906A2	00	7CA ASSEMBLY							
	598 592A Y35-592A	CONE CUP CUP SPCR R		40024 40024 20000		2 2EP 2 1CE 1 04C	90092	40024	5CA ASSEMBLY	EP .0100						
	598 592A X25-598	CONE CUP CONE SPCR A		40024 40024 20000		2 2EP 2 1CE 1 04B	90304	40024	5CA ASSEMBLY	EP .0080						
	598 592A X45-598	CONE CUP CONE SPCR A1		30000 30000 0		2 2EF 2 1CF 1 04B	90112	30000	6CA ASSEMBLY	EP .0090						
	598 592-B	CONE CUP		30001 30001		1 2EF 1 1CH	90081	30070	6CA ASSEMBLY		78 333					
	598-B 592-B	CONE CUP		0 0		1 2EF 1 1CH	90078	0	6CA ASSEMBLY							
	598-B 592-B	CONE CUP		0-30 0-39		1 2EF 1 1CH	90080	0-33	6CA ASSEMBLY							

810ER

## ASSEMBLY IDENTIFICATION REPORT, COPYRIGHTED 1992 BY THE TIMKEN COMPANY

598

MAY

6,

1992 05.18-

PAGE

149

ASSEMBLY  
PART NUMBER

COMPONENT PART NUMBER	DESC	SP TY	COMP INSP	Q-A SGC	COMP ASSY CODE	ASSY INSP	ASSY SGC DESC	END PLAY OR PRELOAD	OBSOLETE DATE
598	CONE		0-32	1	2EF	90079	0-32	6CA ASSEMBLY	
592-B	CUP		0-32	1	1CH				
598	CONE		0-580	1	2EF	90308	0-580	6CA ASSEMBLY	
592-B	CUP		0	1	1CH				
598	CONE		0	2	2EF	90082	0	6CB ASSEMBLY	
592D	CUP		0	1	1CG				
X15-598	CONE SPCR A	20024	2 2EP	90084	20024	SCB ASSEMBLY	EP .0080		
		20024	1 1CB	90114	20024	SCB ASSEMBLY	EP .0100		
		20000	1 04Q	90085	20024	SCB ASSEMBLY	EP .0120		
598	CONE	20024	2 2EP	90241	20649	SCB ASSEMBLY			
592D	CUP	20024	1 1CB						
X15-598	CONE SPCR A	40000	1 04Q						
598	CONE	30000	2 2EF	90262	30000	6CB ASSEMBLY	EP .0020		
592D	CUP	30000	1 1CG	90164	30000	6CB ASSEMBLY	EP .0030		
X15-598	CONE SPCR A	0	1 04Q	90147	30000	6CB ASSEMBLY	EP .0040		
				90083	30000	6CB ASSEMBLY	EP .0050		
598	CONE	40024	2 2EP	90085	40024	SCB ASSEMBLY	EP .0080		
592D	CUP	40024	1 1CB	90160	40024	SCB ASSEMBLY	EP .0100		
X15-598	CONE SPCR A	20000	1 04Q	90087	40024	SCB ASSEMBLY	EP .0120		
				90088	40024	SCB ASSEMBLY	EP .0200		
598	CONE	0	2 2EF	90148	0	6CB ASSEMBLY	EP .0040		
592D	CUP	0	1 1CG						
X15-598	CONE SPCR A	0	1 04Q						
598	CONE	40024	2 2EP	90103	40024	SCB ASSEMBLY	EP .0120		
592D	CUP	40024	1 1CB						
X35-598	CONE SPCR A1	20000	1 04B						
598	CONE	20024	2 2EP	90236	20024	SCB ASSEMBLY	EP .0120		
592DC	CUP	20024	1 1CB						
X15-598	CONE SPCR A	20000	1 04Q						
598	CONE	30000	2 2EF	90186	30000	6CB ASSEMBLY	EP .0040		
592DC	CUP	30000	1 1CG						
X15-598	CONE SPCR A	0	1 04Q						
598	CONE	40024	2 2EP	90200	40024	SCB ASSEMBLY	EP .0100		
592DC	CUP	40024	1 1CB	90188	40024	SCB ASSEMBLY	EP .0120		
X15-598	CONE SPCR A	20000	1 04Q						
598	CONE	20024	1 2EP	90261	20024	SCA ASSEMBLY	EP .0180		
77364	CONE	20024	1 2FA	90309	20024	SCA ASSEMBLY	EP .0180		
592A	CUP	20024	1 1CE						
592A	CUP	20024	1 1CC						
77675	CUP	20024	1 1DL						
X55-598	CONE SPCR A	20000	1 04B						
598A	CONE	0	1 2EF	90089	0	6CA ASSEMBLY			
592A	CUP		1 1CF						
598A	CONE	20157	2 2EP	90302	20214	SCA ASSEMBLY	EP .0020		
592A	CUP	20024	1 1CE						
592-B	CUP	20024	1 1CC						
Y165-592A	CUP SPCR R	20000	1 04C						
X75-598	CONE SPCR A	20000	1 04B						
598A	CONE	0	1 2EF	90176	0	6CA ASSEMBLY			
592-B	CUP	0	1 1CH						
598A	CONE	30000	2 2EF	90221	30000	6CB ASSEMBLY	EP .0040		
592D	CUP	30000	1 1CG	90090	30000	6CB ASSEMBLY	EP .0050		
X15-598	CONE SPCR A	0	1 04Q						

ASSEMBLY IDENTIFICATION REPORT, COPYRIGHTED 1992 BY THE TIMKEN COMPANY											598	MAY	6, 1992	05.18-	PAGE	150
810ER	ASSEMBLY PART NUMBER	COMPONENT PART NUMBER	DESC	SP TY	COMP INSP	Q/A SGC	COMP ASSY CODE	ASSY INSP	ASSY SGC DESC	END PLAY OR PRELOAD	OBSTOLETE DATE					
	X15-598	598A 592D 592A	CONE CUP CONE SPCR A		40024 40024 20000	2 1 1	2EP 1CB 04Q	90091 90212 40024	SCB ASSEMBLY SCB ASSEMBLY	EP .0120 EP .0200						
598-B		598-B 592A	CONE CUP		00 00	1	2EF 1CF	90093 00	7CA ASSEMBLY		91 298					
598H		598H 592	CONE CUP		0 0	1	2EF 1CF	90094 0	6CA ASSEMBLY							
		598H 592A	CONE CUP		0 0	1	2EF 1CF	90095 0	6CA ASSEMBLY							
		598H 592-B	CONE CUP		0 0	1	2EF 1CH	90096 0	6CA ASSEMBLY							
598HB		598HB 592-B	CONE CUP		00 00	1	2EF 1CH	90281 00	7CA ASSEMBLY		90 135					
598X		598X 592A	CONE CUP		0 0	1	2EF 1CF	90229 0	6CA ASSEMBLY							
		598X 592A	CONE CUP		0-284 0-39	1	2EF 1CF	90307 0-284	6CA ASSEMBLY							
		598X 592A	CONE		0-8000 0	1	2EF 1CF	98229 0-8000	6CA ASSEMBLY		86 037					
		598X 592A	CONE CUP		0-8284 0-39	1	2EF 1CF	98307 0-8284	6CA ASSEMBLY		86 037					
NA599		NA599 592AD	CONE CUP		20194 20081	2	2EA 1CB	90097 20194	SCB ASSEMBLY	EP .0210	75 303					
1611		1611 1611C XC2326C T6005	RACE THR CAGE RACE ROLLER		20000 20000 19 010	1	075 062 075	90016 20000	357 THR BRG							
		1611 1611C 16005	RACE THR CAGE ROLLER		2E000 0E000	2	075 062 19 010	9E017 2E000	357 THR BRG							
		1611 1611C 16005	RACE THR CAGE ROLLER		28000 08000	2	075 062 19 010	98017 20000	357 ASSEMBLY		86 037					
1611FS		1611FS 1611-SA 16005	THR BRG RACE ROLLER		20000 20000 25 010	1	075 075 010	90013 20000	357 THR BRG							
		1611FS 1611-SB 16005	THR BRG RACE ROLLER		20000 20000 25 010	1	075 075 010	90014 20000	357 THR BRG							
1611FSA		1611FSA 1611-SA 16005	RACE RACE ROLLER		20000 20000 25 010	1	075 075 010	90017 20000	357 THR BRG							
		1611FSA 1611-SA 16005	RACE RACE ROLLER		20237 20237 25 010	1	075 075 010	90015 20237	357 THR BRG		76 063					
615		615 612	CONE CUP		0 0	1	2BF 1CF	90010 0	6CA ASSEMBLY							
621		621 612	CONE CUP		0 0	1	2BF 1CF	90011 0	6CA ASSEMBLY							
622A		622A 612	CONE CUP		0 0	1	2BF 1CF	90017 0	6CA ASSEMBLY							

ASSEMBLY IDENTIFICATION REPORT, COPYRIGHTED 1992 BY THE TIMKEN COMPANY										622	MAY 6, 1992	05.18-	PAGE	151
810ER	ASSEMBLY PART NUMBER	COMPONENT PART NUMBER	COMP DESC	SP TY	COMP INSP	Q/A SGC	COMP ASSY CODE	ASSY INSP	ASSY SGC DESC	END PLAY OR PRELOAD	OBSTOLETE DATE			
		622A 612-B	CONE CUP		0	1	2BF	90014	0	6CA ASSEMBLY				
623		623 612	CONE CUP		0	1	2BF	90013	0	6CA ASSEMBLY				
		623 612-B	CONE CUP		0	1	2BF	90016	0	6CA ASSEMBLY				
624		624 612	CONE CUP		0	1	2BF	90015	0	6CA ASSEMBLY				
		624 612-B	CONE CUP		0	1	2BF	90017	0	6CA ASSEMBLY				
635		635 632	CONE CUP		0	1	2CF	90091	0	6CA ASSEMBLY				
	X15-635	632D	CONE CUP		40024	2	2CA	90090	40024	5CB ASSEMBLY	EP .0080			
	X15-635	632DC	CONE CUP		40024	1	1CB	90085	40024	5CB ASSEMBLY	EP .0120			
	X15-635	635	CONE CUP		20024	2	2CA	90060	20024	5CB ASSEMBLY	EP .0080			
	X15-635	632DC	CONE CUP		20024	1	1CB							
	X15-635	635	CONE CUP		20000	1	04B							
	X15-635	632DC	CUP		40024	2	2CA	90084	40024	5CB ASSEMBLY	EP .0080			
	X15-635	635	CONE CUP		40024	1	1CB							
	X15-635	632DC	CONE CUP		70000	2	2CA	90065	70000	5CB ASSEMBLY	EP .0080			
	X15-635	635	CONE CUP		20024	1	1CB							
	X15-635	632DC	CONE CUP		20000	1	04B							
636		636 632-B	CONE CUP		0	1	2CF	90010	0	6CA ASSEMBLY				
		636 X15-636	CONE CUP		40024	2	2CL	90011	40024	5CB ASSEMBLY	EP .0080	78 110		
		632D	CONE SPCR		40024	1	1CB							
		636	CONE CUP		20000	1	04A							
637		637 632	CONE CUP		0	1	2CF	90012	0	6CA ASSEMBLY				
		637 632	CONE CUP		0.30	1	1CF	90068	0.30	6CA ASSEMBLY				
		637 632-B	CONE CUP		0	1	2CF	90013	0	6CA ASSEMBLY				
		637 X15-637	CONE CUP		20024	2	2CA	90079	20024	5CB ASSEMBLY	EP .0080			
		632D	CONE SPCR A		20024	1	1CB							
		637 X15-637	CONE CUP		20000	1	04B							
		637 X15-637	CONE CUP		20030	2	2CA	90083	20030	5CB ASSEMBLY	EP .0040			
		632D	CONE SPCR A		20024	1	1CB							
		637 X15-637	CONE CUP		20000	1	04B							
		637 X15-637	CONE CUP		20157	1	1CB							
		637 X15-637	CONE CUP		20000	1	04B							
		637 X15-637	CONE CUP		20030	2	2CA	90073	20358	5CB ASSEMBLY	EP .0050			
		632D	CONE SPCR A		20157	1	1CB							
		637 X15-637	CONE CUP		20000	1	04B							
		637 X15-637	CONE CUP		40024	2	2CA	90074	40024	5CB ASSEMBLY	EP .0080			
		632D	CONE SPCR A		40024	1	1CB							
		637 X15-637	CONE CUP		20000	1	04B							
639		639 632	CONE CUP		0	1	2CF	90014	0	6CA ASSEMBLY				
		632	CONE CUP		0	1	1CF							

ASSEMBLY IDENTIFICATION REPORT, COPYRIGHTED 1992 BY THE TIMKEN COMPANY											639	MAY	6, 1992	05.18-	PAGE
810ER	ASSEMBLY PART NUMBER	COMPONENT PART NUMBER	DESC	SP TY	COMP INSP	Q/A	COMP SGC	ASSY CODE	ASSY INSP	ASSY SGC	END PLAY OR PRELOAD	OBSCOLETE DATE			
	639	CONE			0		2	2CF	90051	0-499	6CB ASSEMBLY		84 207		
	632	CUP			0		2	1CF							
	Y55-632	CUP SPCR Q			0		1	04C							
	X15-639	CONE SPCR A			0		1	04B							
	639	CONE			0		2	2CF	98059	0-8499	6CB ASSEMBLY		84 207		
	632	CUP			0		2	1CF	98051	0-8499	6CB ASSEMBLY		85 206		
	Y55-632	CUP SPCR Q			0-8000		1	04C							
	X15-639	CONE SPCR A			0		1	04B							
	639	CONE			0		1	2CF	90015	0	6CA ASSEMBLY				
	632-B	CUP			0		1	1CH							
	639	CONE			0		2	2CF	90046	0	6CB ASSEMBLY				
	632D	CUP			0		1	1CG							
	639	CONE			20024		2	2CL	90016	20024	5CB ASSEMBLY	EP .0020			
	632D	CUP			20024		1	1CB	90017	20024	5CB ASSEMBLY	EP .0060			
	X15-639	CONE SPCR A			20000		1	04B							
	639	CONE			40024		2	2CL	90050	40024	5CB ASSEMBLY	EP .0080			
	632D	CUP			40024		1	1CB							
	X15-639	CONE SPCR A			20000		1	04B							
	639	CONE			40024		2	2CL	90018	40024	5CB ASSEMBLY	EP .0160			
	632D	CUP			40024		1	1CB							
	X25-639	CONE SPCR A1			20000		1	04B							
639-B	639-B	CONE			00		2	2CF	90058	00	7CB ASSEMBLY				
	632D	CUP			00		1	1CG							
641	641	CONE			0		1	2CF	90055	0	6CA ASSEMBLY				
	632	CUP			0		1	1CF							
	641	CONE			00		1	2CF	906A2	00	7CA ASSEMBLY				
	632	CUP			00		1	1CF							
	X15-641	CONE SPCR A			20024		2	2CL	90075	20024	5CB ASSEMBLY	EP .0080			
	641	CONE			20024		1	1CB							
	632D	CUP			20024		1	04B							
	X15-641	CONE SPCR A			20000		1	04B							
	641	CONE			40024		2	2CL	902A1	20649	5CB ASSEMBLY				
	632D	CUP			40024		1	1CB							
	X15-641	CONE SPCR A			40000		1	04B							
	641	CONE			40024		2	2CL	90019	40024	5CB ASSEMBLY	EP .0120			
	632D	CUP			40024		1	1CB	90081	40024	5CB ASSEMBLY	EP .0240			
	X35-641	CONE SPCR			20000		1	04A							
	641-B	CONE			40024		2	2CL	90062	40024	5CB ASSEMBLY	EP .0160	78 110		
	632	CUP			40024		1	1CB							
	X35-641	CONE SPCR			20000		1	04A							
641-B	641-B	CONE			00		1	2CF	90047	00	7CA ASSEMBLY		91 256		
	632	CUP			00		1	1CF							
642	642	CONE			0		1	2CF	90020	0	6CA ASSEMBLY				
	632	CUP			0		1	1CF							
	642	CONE			30000		2	2CF	90059	30000	6CB ASSEMBLY	EP .0050			
	632D	CUP			30000		1	1CG							
	X15-642	CONE SPCR A			0		1	04B							
	642	CONE			0		1	2CF	90045	0	6CA ASSEMBLY				
	633	CUP			0		1	1CF							
	643	CONE			0		1	2CF	90021	0	6CA ASSEMBLY				
	632	CUP			0		1	1CF							
	643-B	CONE			0		1	2CF	90022	0	6CA ASSEMBLY				
	632-B	CUP			0		1	1CH							

ASSEMBLY IDENTIFICATION REPORT. COPYRIGHTED 1992 BY THE TIMKEN COMPANY											643	MAY 6, 1992	05.18-	PAGE	153
810ER	ASSEMBLY PART NUMBER	COMPONENT PART NUMBER	DESC	SP TY	COMP INSP	Q/A	COMP SGC	ASSY CODE	ASSY INSP	ASSY SGC	ASSY DESC	END PLAY OR PRELOAD	OBSOLETE DATE		
	643 632D	CONE CUP		0 0	2 2CF	90023	0	6CB ASSEMBLY							
	643 632D X15-632 XIS-643	CONE CUP CUP SPCR R CONE SPCR A		40024 40024 20000 20000	4 2CL 2 1CG 1 04C 2 04B	90078	40024	5CC ASSEMBLY	EP .0160						
	643 632D X15-632 X25-643	CONE CUP CUP SPCR R CONE SPCR A1		30000 30000 0 0	4 2CF 2 1CG 1 04C 2 04B	90048	30000	6CC ASSEMBLY	EP .0080						
	643 632D X15-643	CONE CUP CONE SPCR A		20024 20024 20000	2 2CL 1 1CG 1 04B	90025 90026 90027 90028	20024 20024 20024 20024	5CB ASSEMBLY 5CB ASSEMBLY 5CB ASSEMBLY 5CB ASSEMBLY	EP .0040 EP .0080 EP .0120 EP .0160						
	643 632D X15-643	CONE CUP CONE SPCR A		30000 30000 0	2 2CF 1 1CG 1 04B	90052 90142	30000 30000	6CB ASSEMBLY 6CB ASSEMBLY	EP .0050 EP .0080						
	643 632D X15-643	CONE CUP CONE SPCR A		40024 40024 2E000	2 2CL 1 1CG 1 04B	9E029	4E024	5CB ASSEMBLY	EP .0120						
	643 632D X15-643	CONE CUP CONE SPCR A		40024 40024 20000	2 2CL 1 1CG 1 04B	90086 90029	40024 40024	5CB ASSEMBLY 5CB ASSEMBLY	EP .0100 EP .0120	91 231					
	643 632D X25-643	CONE CUP CONE SPCR A1		40024 40024 20000	2 2CL 1 1CG 1 04B	90071 90070	40024 40024	5CB ASSEMBLY 5CB ASSEMBLY	EP .0120 EP .0160						
	643 632DC X15-643	CONE CUP CONE SPCR A		30000 30000 0	2 2CF 1 1CG 1 04B	90057 90076	30000 30000	6CB ASSEMBLY 6CB ASSEMBLY	EP .0030 EP .0050						
	643 632DC X15-643	CONE CUP CONE SPCR A		40024 40024 20000	2 2CL 1 1CG 1 04B	90064 90082	40024 40024	5CB ASSEMBLY 5CB ASSEMBLY	EP .0080 EP .0120						
	643 633	CONE CUP		20024 20024	1 2CL 1 1CA	90087	20211	5CA ASSEMBLY							
	643 633	CONE CUP		0 0	1 2CF 1 1CF	90030	0	6CA ASSEMBLY							
	643 HM212046 633 HM212011 X35-643	CONE CUP CUP CONE SPCR A		40024 40024 40024 40024 20000	1 2CL 1 1CA 1 1CE 1 04B	90056	40024	5CA ASSEMBLY	EP .0160						
643-B	643-B 632	CONE CUP		00 00	1 2CF 1 1CF	90077	00	7CA ASSEMBLY							
NA643	NA643 632D	CONE CUP		20194 20081	2 2CA 1 1CB	90032	20194	5CB ASSEMBLY	EP .0220						
	NA643 632D	CONE CUP		30000 30001	2 2CF 1 1CG	90042	30000	6CB ASSEMBLY	EP .0040						
NA643 SW	NA643-SW 632D	CONE CUP		20194 20081	2 2CA 1 1CB	90033	20194	5CB ASSEMBLY	EP .0220						
644	644 632	CONE CUP		0 0	1 2CF 1 1CF	90053	0	6CA ASSEMBLY							
	644 632	CONE CUP		0-30 0	1 2CF 1 1CF	90069	0-30	6CA ASSEMBLY							

ASSEMBLY IDENTIFICATION REPORT, COPYRIGHTED '992 BY THE TIMKEN COMPANY										644	MAY	6, 1992	05.18-	PAGE
ASSEMBLY PART NUMBER	COMPONENT PART NUMBER	DESC	SP TY	COMP INSP	Q/A	COMP SGC	ASSY CODE	ASSY INSP	ASSY SGC	ASSY DESC	END PLAY OR PRELOAD	OBSCU DATE		
	644	CONE CUP		0-174	1	2CF 0	90049	0-174	6CA ASSEMBLY					
	632													
	644	CONE CUP		00	1	2CF 00	906A1	00	7CA ASSEMBLY					
	632													
	644	CONE CUP		0	1	2CF 0	90034	0	6CA ASSEMBLY					
	632-B													
	644	CONE CUP		30000	2	2CF 30000	90072	30000	6CB ASSEMBLY	EP .0050				
	632D													
	X15-644	CONE SPCR A1		0	1	1CG 04B								
	644	CONE CUP		40024	2	2CL 40024	90044	40024	5CB ASSEMBLY	EP .0100				
	632D													
	X15-644	CONE SPCR A1		20000	1	04B								
	644	CONE CUP		20024	2	2CL 20024	90035	20024	5CB ASSEMBLY	EP .0040				
	632D													
	X15-645	CONE SPCR A		20000	1	04B	90063	20024	5CB ASSEMBLY	EP .0070				
	644	CONE CUP		40024	2	2CL 40024	90067	40024	5CB ASSEMBLY	EP .0080				
	632D													
	X15-645	CONE SPCR A		20000	1	04B								
	644	CONE CUP		0	1	2CF 0	90036	0	6CA ASSEMBLY					
	632													
644-B	644-B	CONE CUP		00	1	2CF 00	90037	00	7CA ASSEMBLY					
	632													
545	645	CONE CUP		0	1	2CF 0	90038	0	6CA ASSEMBLY					
	632													
	645	CONE CUP		0	1	2CF 0	90039	0	6CA ASSEMBLY					
	632-B													
	645	CONE CUP		0	2	2CF 1	90054	0	6CB ASSEMBLY					
	632D													
	X15-645	CONE SPCR A		20000	1	04B								
	645	CONE CUP		0	2	2CF 1	90088	0	6CB ASSEMBLY	EP .0080				
	632D													
	X15-645	CONE SPCR A		0	1	04B								
	645-B	CONE CUP		00	2	2CF 1	90080	00	7CB ASSEMBLY		90 129			
	632D													
	645-B	CONE CUP		00	2	2CF 1	90089	00	7CB ASSEMBLY	EP .0020	90 129			
	632D													
	X15-645	CONE SPCR A		00	1	04B								
NA646-SW	NA646 SW	CONE CUP		30441	2	2CZ 1	90010	30441	6CZ ASSEMBLY	EP .0010-.0030				
	K516780			30441		1CZ								
	K516791	CLOSURE			2	090								
655	655	CONE CUP		40024	1	2DA 1	9F499	4F024	5CA ASSEMBLY					
	652			40024		1CA								
	655	CONE CUP		0	1	2DF 1	90010	0	6CA ASSEMBLY					
	652													
	655	CONE CUP		0-30	1	2DF 1	90011	0-33	6CA ASSEMBLY					
	652			0-30										
	655-B	CONE CUP		0	1	2DF 1	90012	0	6CA ASSEMBLY					
	652-B			0	1	1CH								