



30208...B16
30210...C16
30212...D16
30214...E16
30217...F16
30221...G16
30304...H16
30308...I16
30311...J16
30315...K16
31306...L16
31308...M16
31309...N16
31309...O16

| ASSEMBLY PART NUMBER | COMPONENT PART NUMBER | DESC | SP TY | COMP INSP | Q-A | COMP SGC | ASSY CODE | ASSY INSP | SGC | ASSY DESC | END PLAY OP PPELOAD | OBsolete DATE |
|----------------------|------------------------|-------------|--------|----------------|-----|------------|-------------------------|-------------------------|-------------------|----------------------------------|---------------------|----------------------------|
| | X30208 Y30208 | CONE CUP | | K0227 K0227 | 1 | 2AA 1BA | 90KA5 | K0227 | 580 | ASSEMBLY | | |
| | X30208 Y30208 | CONE CUP | | NF000 NF000 | 1 | 2AA 1BA | 92HA2 | NF000 | 580 | ASSEMBLY | | |
| | X30208 Y30208 | CONE CUP | | V2000 V2000 | 1 | 2AF 1BF | 90V50 | V2000 | 580 | ASSEMBLY | | |
| | X30208 Y30208 | CONE CUP | | 41024 41024 | 1 | 2AA 1BA | 91B50 | 41024 | 580 | ASSEMBLY | | 72 362 |
| 30209 | X30209 Y30209 | CONE CUP | | CF000 CF000 | 1 | 2AF 1BF | 92CA1 | CF000 | 580 | ASSEMBLY | | 90 037 |
| | X30209 Y30209 | CONE CUP | | D1000 D1000 | 1 | 2AF 1BF | 91D50 | D1000 | 580 | ASSEMBLY | | |
| | X30209 Y30209 | CONE CUP | | E1000 E1000 | 1 | 2AF 1BF | 91E50 | E1000 | 580 | ASSEMBLY | | |
| | X30209 Y30209 | CONE CUP | | H1000 H1000 | 1 | 2AA 1BA | 91H50 | H0000 | 580 | ASSEMBLY | | |
| | X30209 Y30209 | CONE CUP | | H1000 H1000 | 1 | 2AA 1BA | 92H50 90H50 | H1000 H1000 | 580 580 | ASSEMBLY ASSEMBLY | | 89 228 77 174 |
| | X30209 Y30209 | CONE CUP | | KE000 KE000 | 1 | 2AA 1BA | 9EK41 | KE000 | 580 | ASSEMBLY | | |
| | X30209 Y30209 | CONE CUP | | KF000 KF000 | 1 | 2AA 1BA | 90KA1 | K2000 | 580 | ASSEMBLY | | |
| | X30209 Y30209 | CONE CUP | | 41024 41024 | 1 | 2AA 1BA | 91B50 | 41024 | 580 | ASSEMBLY | | 72 362 |
| 30209H | X30209H Y30209 | CONE CUP | | E1000 E1000 | 1 | 2AF 1BF | 91E50 | E1000 | 580 | ASSEMBLY | | |
| 30210 | X30210 Y30210 | CONE CUP | | CF000 CF000 | 1 | 2BF 1BF | 92CA1 | CF000 | 580 | ASSEMBLY | | 91 022 |
| | X30210 Y30210 | CONE CUP | | D1000 D1000 | 1 | 2BF 1BF | 91D50 | D1000 | 580 | ASSEMBLY | | |
| | X30210 Y30210 | CONE CUP | | E1000 E1000 | 1 | 2BF 1BF | 91E50 | E1000 | 580 | ASSEMBLY | | |
| | X30210 Y30210 | CONE CUP | | H1000 H1000 | 1 | 2BA 1BA | 90H50 91H50 92H50 | H1000 H1000 H1000 | 580 580 580 | ASSEMBLY ASSEMBLY ASSEMBLY | | 77 174 86 219 89 228 |
| | X30210 Y30210 | CONE CUP | | H1301 H1301 | 1 | 2BA 580 | 91H01 | H1000 | 580 | ASSEMBLY | | |
| | X30210 Y30210 | CONE CUP | | KF000 KF000 | 1 | 2BA 1BA | 92KA1 | K2000 | 580 | ASSEMBLY | | |
| | X30210 Y30210 | CONE CUP | | KF000 KF000 | 1 | 2BA 1BA | 92KA9 | K2702 | 580 | ASSEMBLY | | |
| | X30210 Y30210 | CONE CUP | | V1000 V1000 | 1 | 2BF 1BF | 91V50 | V1000 | 580 | ASSEMBLY | | |
| | X30210 Y30210 | CONE CUP | | 41024 41024 | 1 | 2BA 1BA | 91B50 | 41024 | 580 | ASSEMBLY | | 72 362 |
| | X30210 Y30210 | CONE CUP | | H1395 H1395 | 2 | 2BA 1BA | 91H50 | H1395 | 580 | ASSEMBLY | EP .0050 | 86 219 |
| | X15 30210 Y15 30210 | CONE CUP | SPCR R | 2F000 2F000 | 1 | 04A 01B | | | | | | |

| ASSEMBLY PART NUMBER | COMPONENT PART NUMBER | DESC | SP TY | COMP INSP | Q/A | COMP SGC | ASSY CODE | ASSY INSP | SGC | ASSY DESC | END PLAY OR PRELOAD | OBSOLETE DATE |
|-------------------------|--------------------------|------|----------|--------------|-----|-------------|--------------|--------------|-----|--------------|------------------------|------------------|
| | X30210 | CONE | | KF395 | 2 | 2BA | 92KA3 | K2395 | 580 | ASSEMBLY | EP .0050 | |
| | Y30210 | CUP | | KF395 | 2 | 1BA | | | | | | |
| | X15-30210 | CONE | SPCR A | 2F000 | 1 | 04A | | | | | | |
| | Y15-30210 | CUP | SPCR R | 2F000 | 1 | 04B | | | | | | |
| XGA30210 | XGA30210 | CONE | | KF000 | 1 | 2BA | 92KA1 | K200Q | 580 | ASSEMBLY | | |
| | Y30210 | CUP | | KF000 | 1 | 1BA | | | | | | |
| 30211 | X30211 | CONE | | BE000 | 1 | 2BF | 9EBA3 | BE000 | 580 | ASSEMBLY | | |
| | Y30211 | CUP | | BE000 | 1 | 1BF | | | | | | |
| | X30211 | CONE | | CF000 | 1 | 2BF | 92CA1 | CF000 | 580 | ASSEMBLY | | |
| | Y30211 | CUP | | CF000 | 1 | 1BF | | | | | | |
| | X30211 | CONE | | D1000 | 1 | 2BF | 91D50 | D1000 | 580 | ASSEMBLY | | |
| | Y30211 | CUP | | D1000 | 1 | 1BF | | | | | | |
| | X30211 | CONE | | E1000 | 1 | 2BF | 91E50 | E1000 | 580 | ASSEMBLY | | |
| | Y30211 | CUP | | E1000 | 1 | 1BF | | | | | | |
| | X30211 | CONE | | E1227 | 1 | 2BF | 91E27 | E1227 | 580 | ASSEMBLY | | |
| | Y30211 | CUP | | E1227 | 1 | 1BF | | | | | | |
| | X30211 | CONE | | H1000 | 1 | 2BA | 90H50 | H1000 | 580 | ASSEMBLY | | 77 174 |
| | Y30211 | CUP | | H1000 | 1 | 1BA | 92H50 | H1000 | 580 | ASSEMBLY | | 90 030 |
| | | | | | | | 91H50 | H1000 | 580 | ASSEMBLY | | 86 219 |
| | X30211 | CONE | | H2000 | 1 | 2BA | 92HA4 | H2702 | 580 | ASSEMBLY | | |
| | Y30211 | CUP | | H2000 | 1 | 1BA | | | | | | |
| | X30211 | CONE | | H2514 | 1 | 2BA | 92HA2 | H2514 | 580 | ASSEMBLY | | 86 044 |
| | Y30211 | CUP | | H2514 | 1 | 1BA | | | | | | |
| | X30211 | CONE | | KF000 | 1 | 2BA | 90KA1 | KU000 | 580 | ASSEMBLY | | |
| | Y30211 | CUP | | KF000 | 1 | 1BA | | | | | | |
| | X30211 | CONE | | KF000 | 1 | 2BA | 92KA1 | K2000 | 580 | ASSEMBLY | | |
| | Y30211 | CUP | | KF000 | 1 | 1BA | | | | | | |
| | X30211 | CONE | | K0227 | 1 | 2BA | 90KA7 | K0227 | 580 | ASSEMBLY | | |
| | Y30211 | CUP | | K0227 | 1 | 1BA | | | | | | |
| | X30211 | CONE | | NF000 | 1 | 2BA | 92NA2 | NF000 | 580 | ASSEMBLY | | |
| | Y30211 | CUP | | NF000 | 1 | 1BA | | | | | | |
| | X30211 | CONE | | 41024 | 1 | 2BA | 91850 | 41024 | 580 | ASSEMBLY | | 72 362 |
| | Y30211 | CUP | | 41024 | 1 | 1BA | | | | | | |
| 30212 | X30212 | CONE | | CF000 | 1 | 2BF | 92CA1 | CF000 | 580 | ASSEMBLY | | 91 022 |
| | Y30212 | CUP | | CF000 | 1 | 1BF | | | | | | |
| | X30212 | CONE | | D1000 | 1 | 2BF | 91D50 | D1000 | 580 | ASSEMBLY | | |
| | Y30212 | CUP | | D1000 | 1 | 1BF | | | | | | |
| | X30212 | CONE | | E1000 | 1 | 2BF | 91E50 | E1000 | 580 | ASSEMBLY | | |
| | Y30212 | CUP | | E1000 | 1 | 1BF | | | | | | |
| | X30212 | CONE | | E1227 | 1 | 2BF | 91E27 | E1227 | 580 | ASSEMBLY | | |
| | Y30212 | CUP | | E1227 | 1 | 1BF | | | | | | |
| | X30212 | CONE | | HF514 | 1 | 2BA | 92HA3 | HF514 | 580 | ASSEMBLY | | |
| | Y30212 | CUP | | HF514 | 1 | 1BA | | | | | | |
| | X30212 | CONE | | HF516 | 1 | 2BA | 92HA4 | HF516 | 580 | ASSEMBLY | | |
| | Y30212 | CUP | | HF516 | 1 | 1BA | | | | | | |
| | X30212 | CONE | | H1000 | 1 | 2BA | 92H50 | H1000 | 580 | ASSEMBLY | | 89 228 |
| | Y30212 | CUP | | H1000 | 1 | 1BA | 91H50 | H1000 | 580 | ASSEMBLY | | 86 220 |
| | | | | | | | 90H50 | H1000 | 580 | ASSEMBLY | | 77 174 |

| ASSEMBLY PART NUMBER | COMPONENT PART NUMBER | DESC | SP TY | COMP INSP | Q/A | COMP SGC | ASSY CODE | ASSY INSP | SGC | ASSY DESC | END PLAY OR PRELOAD | OBSOLETE DATE |
|-------------------------|-------------------------------|-------------------------|----------|-------------------------|-----|-------------------------|---------------------------|-------------------------|-------------------|----------------------------------|------------------------|------------------|
| | X30212 Y30212 | CONE CUP | | KF000 KF000 | | 1 2BA 1 1BA | 92KA1 | K2000 | 580 | ASSEMBLY | | |
| | X30212 Y30212 | CONE CUP | | KF000 KF000 | | 1 2BA 1 1BA | 92KA9 | K2702 | 580 | ASSEMBLY | | |
| | X30212 Y30212 | CONE CUP | | NF000 NF000 | | 1 2BA 1 1BA | 92NA2 | N2000 | 580 | ASSEMBLY | | |
| | X30212 Y30212 | CONE CUP | | V1000 V1000 | | 1 2BF 1 1BF | 91V50 | V1000 | 580 | ASSEMBLY | | |
| | X30212 Y30212 | CONE CUP | | 41024 41024 | | 1 2BA 1 1BA | 91B50 | 41024 | 580 | ASSEMBLY | | 72 362 |
| 30213 | X30213 Y30213 | CONE CUP | | D1000 D1000 | | 1 2CF 1 1CF | 91D50 | D1000 | 580 | ASSEMBLY | | |
| | X30213 Y30213 | CONE CUP | | E1000 E1000 | | 1 2CF 1 1CF | 91E50 | E1000 | 580 | ASSEMBLY | | |
| | X30213 Y30213 | CONE CUP | | E1227 E1227 | | 1 2CF 1 1CF | 51E27 | E1227 | 580 | ASSEMBLY | | |
| | X30213 Y30213 | CONE CUP | | H1000 H1000 | | 1 2CA 1 1CA | 91H50 91H50 | H1000 H1000 | 580 580 | ASSEMBLY ASSEMBLY | | 89 738 |
| | X30213 Y30213 | CONE CUP | | KF000 KF000 | | 1 2CA 1 1CA | 92KA1 | K2000 | 580 | ASSEMBLY | | |
| | X30213 Y30213 | CONE CUP | | K0227 K0227 | | 1 2CA 1 1CA | 90KA3 | K0227 | 580 | ASSEMBLY | | |
| | X30213 Y30213 | CONE CUP | | V1000 V1000 | | 1 2CF 1 1CF | 91V50 | V1000 | 580 | ASSEMBLY | | |
| | X30213 Y30213 | CONE CUP | | 41024 41024 | | 1 2CA 1 1CA | 91B50 | 41024 | 580 | ASSEMBLY | | 72 362 |
| | X30213 Y30213 Y15-30213 | CONE CUP CUP SPCR | | H1000 H1000 2F000 | | 2 2CA 2 1CA 1 04C | 91H51 | H1000 | 580 | ASSEMBLY | EP .0050 | |
| | X30213 Y30213 Y25-30213 | CONE CUP CUP SPCR | | H1000 H1000 2F000 | | 2 2CA 2 1CA 1 04C | 92H52 91H52 | H1000 H1000 | 580 580 | ASSEMBLY ASSEMBLY | EP .0050 EP .0050 | |
| | X30213 Y30213 Y25-30213 | CONE CUP CUP SPCR | | KF000 KF000 2F000 | | 2 2CA 2 1CA 1 04C | 92KA2 | K2000 | 580 | ASSEMBLY | EP .0050 | |
| 30214 | X30214 Y30214 | CONE CUP | | CF000 CF000 | | 1 2CF 1 1CF | 92CA2 9FCA1 | CF000 CF000 | 580 580 | ASSEMBLY ASSEMBLY | | 89 118 89 118 |
| | X30214 Y30214 | CONE CUP | | E1000 E1000 | | 1 2CF 1 1CF | 91E50 | E1000 | 580 | ASSEMBLY | | |
| | X30214 Y30214 | CONE CUP | | H1000 H1000 | | 1 2CA 1 1CA | 91H50 92H50 90H50 | H1000 H1000 H1000 | 580 580 580 | ASSEMBLY ASSEMBLY ASSEMBLY | | 90 010 77 174 |
| | X30214 Y30214 | CONE CUP | | KF000 KF000 | | 1 2CA 1 1CA | 92KA1 | K2000 | 580 | ASSEMBLY | | |
| | X30214 Y30214 | CONE CUP | | KF000 KF000 | | 1 2CA 1 1CA | 92KA9 | K2702 | 580 | ASSEMBLY | | |
| | X30214 Y30214 | CONE CUP | | 41024 41024 | | 1 2CA 1 1CA | 91B50 | 41024 | 580 | ASSEMBLY | | 72 362 |

| ASSEMBLY PART NUMBER | COMPONENT PART NUMBER | DESC | SP TY | COMP INSP | Q/A | COMP SGC | ASSY CODE | ASSY INSP | SGC | ASSY DESC | END PLAY OR PRELOAD | OBSOLETE DATE |
|----------------------|-----------------------|-----------|-------|-----------|-----|----------|-----------|-----------|-----|-----------|---------------------|---------------|
| | X30214 | CONE | | H1395 | 2 | 2CA | 91H51 | H1395 | 580 | ASSEMBLY | EP .0060 | |
| | Y30214 | CUP | | H1395 | 2 | 1CA | | | | | | |
| | X15-30214 | CONE SPCR | AA | 2F000 | 1 | 04B | | | | | | |
| | Y15-30214 | CUP SPCR | R | 2F000 | 1 | 04C | | | | | | |
| | X30214 | CONE | | KF395 | 2 | 2CA | 92KA4 | K2395 | 580 | ASSEMBLY | EP .0060 | |
| | Y30214 | CUP | | KF395 | 2 | 1CA | | | | | | |
| | X15-30214 | CONE SPCR | AA | 2F000 | 1 | 04B | | | | | | |
| | Y15-30214 | CUP SPCR | R | 2F000 | 1 | 04C | | | | | | |
| 30215 | X30215 | CONE | | E1000 | 1 | 2CF | 91E50 | E1000 | 580 | ASSEMBLY | | |
| | Y30215 | CUP | | E1000 | 1 | 1CF | | | | | | |
| | X30215 | CONE | | E1227 | 1 | 2CF | 91E27 | E1227 | 580 | ASSEMBLY | | |
| | Y30215 | CUP | | E1227 | 1 | 1CF | | | | | | |
| | X30215 | CONE | | HF514 | 1 | 2CA | 92HA1 | HF514 | 580 | ASSEMBLY | | |
| | Y30215 | CUP | | HF514 | 1 | 1CA | | | | | | |
| | X30215 | CONE | | H1000 | 1 | 2CA | 91H50 | H1000 | 580 | ASSEMBLY | | 86 220 |
| | Y30215 | CUP | | H1000 | 1 | 1CA | 92H50 | H1000 | 580 | ASSEMBLY | | 90 010 |
| | | | | | | | 90H50 | H1000 | 580 | ASSEMBLY | | 77 174 |
| | X30215 | CONE | | KF000 | 1 | 2CA | 92KA1 | K2000 | 580 | ASSEMBLY | | |
| | Y30215 | CUP | | KF000 | 1 | 1CA | | | | | | |
| | X30215 | CONE | | KF000 | 1 | 2CA | 92KA9 | K2702 | 580 | ASSEMBLY | | |
| | Y30215 | CUP | | KF000 | 1 | 1CA | | | | | | |
| | X30215 | CONE | | NF000 | 1 | 2CA | 92NA3 | N2000 | 580 | ASSEMBLY | | |
| | Y30215 | CUP | | NF000 | 1 | 1CA | | | | | | |
| | X30215 | CONE | | 41024 | 1 | 2CA | 91850 | 41024 | 580 | ASSEMBLY | | 72 362 |
| | Y30215 | CUP | | 41024 | 1 | 1CA | | | | | | |
| 30216 | X30216 | CONE | | E1000 | 1 | 2CF | 92E50 | E1000 | 580 | ASSEMBLY | | |
| | Y30216 | CUP | | E1000 | 1 | 1CF | 91E50 | E1000 | 580 | ASSEMBLY | | |
| | X30216 | CONE | | H1000 | 1 | 2CA | 90H50 | H1000 | 580 | ASSEMBLY | | 77 174 |
| | Y30216 | CUP | | H1000 | 1 | 1CA | 91H50 | H1000 | 580 | ASSEMBLY | | 86 220 |
| | | | | | | | 92H50 | H1000 | 580 | ASSEMBLY | | 89 228 |
| | X30216 | CONE | | KF000 | 1 | 2CA | 92KA1 | K2000 | 580 | ASSEMBLY | | |
| | Y30216 | CUP | | KF000 | 1 | 1CA | | | | | | |
| | X30216 | CONE | | KF000 | 1 | 2CA | 92KA9 | K2702 | 580 | ASSEMBLY | | |
| | Y30216 | CUP | | KF000 | 1 | 1CA | | | | | | |
| | X30216 | CONE | | K0227 | 1 | 2CA | 90KA3 | K0227 | 580 | ASSEMBLY | | |
| | Y30216 | CUP | | K0227 | 1 | 1CA | | | | | | |
| | X30216 | CONE | | NF000 | 1 | 2CA | 92NA2 | NF000 | 580 | ASSEMBLY | | |
| | Y30216 | CUP | | NF000 | 1 | 1CA | | | | | | |
| | X30216 | CONE | | V1000 | 1 | 2CF | 92V50 | V1000 | 580 | ASSEMBLY | | |
| | Y30216 | CUP | | V1000 | 1 | 1CF | 91V50 | V1000 | 580 | ASSEMBLY | | |
| | X30216 | CONE | | 41024 | 1 | 2CA | 91850 | 41024 | 580 | ASSEMBLY | | 72 362 |
| | Y30216 | CUP | | 41024 | 1 | 1CA | | | | | | |
| K30216 | K30216 | TUBE | | | 1 | 454 | 90010 | | 454 | TUBE ASSY | | |
| | K44734 | BACK RING | | | 2 | 419 | | | | | | |
| 30217 | X30217 | CONE | | H1000 | 1 | 2DA | 91H50 | H1000 | 580 | ASSEMBLY | | 86 220 |
| | Y30217 | CUP | | H1000 | 1 | 1CA | 92H50 | H1000 | 580 | ASSEMBLY | | 89 228 |
| | | | | | | | 90H50 | H1000 | 580 | ASSEMBLY | | 77 174 |
| | X30217 | CONE | | KF000 | 1 | 2DA | 92KA1 | K2000 | 580 | ASSEMBLY | | |
| | Y30217 | CUP | | KF000 | 1 | 1CA | | | | | | |

| ASSEMBLY PART NUMBER | COMPONENT PART NUMBER | DESC | SP TY | COMP INSP | Q/A | COMP SGC | ASSY CODE | ASSY INSP | SGC | ASSY DESC | END PLAY OR PRELOAD | OR OBSOLETE DATE | |
|-------------------------|--------------------------|------------|----------|--------------|-------|-------------|--------------|--------------|----------|--------------|------------------------|------------------------|--------|
| 30218 | X30217 | CONE | | KF000 | 1 | 2DA | 92KA9 | K2702 | 580 | ASSEMBLY | | | |
| | Y30217 | CUP | | KF000 | 1 | 1CA | | | | | | | |
| | X30217 | CONE | | 41024 | 1 | 2DA | 91850 | 41024 | 580 | ASSEMBLY | | 72 362 | |
| | Y30217 | CUP | | 41024 | 1 | 1CA | | | | | | | |
| | X30218 | CONE | | E1000 | 1 | 2EF | 91E50 | E1000 | 580 | ASSEMBLY | | | |
| | Y30218 | CUP | | E1000 | 1 | 1CF | | | | | | | |
| | X30218 | CONE | | E1227 | 1 | 2EF | 91E27 | E1227 | 580 | ASSEMBLY | | | |
| | Y30218 | CUP | | E1227 | 1 | 1CF | | | | | | | |
| | X30218 | CONE | | H1000 | 1 | 2EA | 91H50 | H1000 | 580 | ASSEMBLY | | 86 220 | |
| | Y30218 | CUP | | H1000 | 1 | 1CA | 90H50 | H1000 | 580 | ASSEMBLY | | 77 174 | |
| | | | | | | | | 92H50 | H1000 | 580 | ASSEMBLY | | 90 010 |
| | X30218 | CONE | | KF000 | 1 | 2EA | 92KA1 | K2000 | 580 | ASSEMBLY | | | |
| | Y30218 | CUP | | KF000 | 1 | 1CA | | | | | | | |
| | 30219 | X30218 | CONE | | H1000 | 2 | 2EA | 91H51 | H1000 | 580 | ASSEMBLY | EP .0040 | |
| Y30218 | | CUP | | H1000 | 1 | 1CA | | | | | | | |
| Y15-30218 | | CUP SPCR Q | | 20000 | 1 | 04C | | | | | | | |
| X30218 | | CONE | | 41024 | 2 | 2EA | 91851 | 41024 | 580 | ASSEMBLY | EP .0040 | 72 362 | |
| Y30218 | | CUP | | 41024 | 2 | 1CA | | | | | | | |
| Y15-30218 | | CUP SPCR Q | | 20000 | 1 | 04C | | | | | | | |
| X30218 | | CONE | | 42024 | 2 | 2EA | 92851 | 42024 | 580 | ASSEMBLY | EP .0040 | 72 362 | |
| Y30218 | | CUP | | 42024 | 2 | 1CA | | | | | | | |
| Y15-30218 | | CUP SPCR Q | | 20000 | 1 | 04C | | | | | | | |
| X30219 | | CONE | | CF000 | 1 | 2FF | 92CA1 | CF000 | 580 | ASSEMBLY | | | |
| Y30219 | | CUP | | CF000 | 1 | 1DF | | | | | | | |
| X30219 | | CONE | | D1000 | 1 | 2FF | 91D50 | D1000 | 580 | ASSEMBLY | | | |
| Y30219 | | CUP | | D1000 | 1 | 1DF | | | | | | | |
| X30219 | | CONE | | H1000 | 1 | 2FA | 90H50 | H1000 | 580 | ASSEMBLY | | 77 174 | |
| Y30219 | CUP | | H1000 | 1 | 1DA | 92H50 | H1000 | 580 | ASSEMBLY | | 90 030 | | |
| | | | | | | | 91H50 | H1000 | 580 | ASSEMBLY | | 86 220 | |
| 30220 | X30219 | CONE | | KE000 | 1 | 2FA | 9EKA1 | KE000 | 580 | ASSEMBLY | | | |
| | Y30219 | CUP | | KE000 | 1 | 1DA | | | | | | | |
| | X30219 | CONE | | KF000 | 1 | 2FA | 9UKA1 | KU000 | 580 | ASSEMBLY | | | |
| | Y30219 | CUP | | KF000 | 1 | 1DA | | | | | | | |
| | X30219 | CONE | | KF000 | 1 | 2FA | 92KA1 | K2000 | 580 | ASSEMBLY | | | |
| | Y30219 | CUP | | KF000 | 1 | 1DA | | | | | | | |
| | X30219 | CONE | | KF000 | 1 | 2FA | 92KA9 | K2702 | 580 | ASSEMBLY | | | |
| | Y30219 | CUP | | KF000 | 1 | 1DA | | | | | | | |
| | X30219 | CONE | | 41024 | 1 | 2FA | 91850 | 41024 | 580 | ASSEMBLY | | 72 362 | |
| | Y30219 | CUP | | 41024 | 1 | 1DA | | | | | | | |
| | X30220 | CONE | | K0025 | 1 | 2FA | 90KA1 | K0025 | 580 | ASSEMBLY | | | |
| | Y30220 | CUP | | K0000 | 1 | 1DA | | | | | | | |
| | X30220 | CONE | | 41024 | 1 | 2FA | 91850 | 41024 | 580 | ASSEMBLY | | 72 362 | |
| | Y30220 | CUP | | 41024 | 1 | 1DA | | | | | | | |
| 30221 | X30221 | CONE | | H1000 | 1 | 2GA | 91H50 | H1000 | 580 | ASSEMBLY | | 86 220 | |
| | Y30221 | CUP | | H1000 | 1 | 1DA | 90H50 | H1000 | 580 | ASSEMBLY | | 77 174 | |

| ASSEMBLY PART NUMBER | COMPONENT PART NUMBER | DESC | SP TY | COMP INSP | Q/A | COMP SGC | ASSY CODE | ASSY INSP | SGC | ASSY DESC | END PLAY OR PRELOAD | OBSOLETE DATE |
|-------------------------|---|--|----------|----------------|--|--|-------------------------|-------------------------|-----|----------------------------------|------------------------|----------------------------|
| | X30221 Y30221 | CONE CUP | | KF000 KF000 | 1 | 2GA 1DA | 92KA1 | KF000 | 580 | ASSEMBLY | | |
| | X30221 Y30221 | CONE CUP | | K0025 K0000 | 1 | 2GA 1DA | 90KA1 | K0025 | 5DA | ASSEMBLY | | |
| T30221A | 09067 09195 T27362 T30221A K36060 K52007 K104322 K104323 K104324 K104325 | CONE CUP FLINGER TUBE CLOSURE CLOSURE CONV ROLL TUBE ALEM FIT CONV ROLL | | 40024 40024 | 2 2 2 1 2 2 2 1 2 1 | 2AD 1AD 412 451 411 411 490 450 469 490 | 90010 | 40024 | 451 | TUBE ASSY | | |
| 30222 | X30222 Y30222 | CONE CUP | | H1000 H1000 | 1 | 2GA 1DA | 91H50 90H50 92H50 | H1000 H1000 H1000 | 580 | ASSEMBLY ASSEMBLY ASSEMBLY | | 92 055 77 174 |
| | X30222 Y30222 | CONE CUP | | 41024 41024 | 1 | 2GA 1DA | 91850 | 41024 | 580 | ASSEMBLY | | 72 362 |
| 30224 | X30224 Y30224 | CONE CUP | | H1000 H1000 | 1 | 2GA 1EA | 92H50 91H50 90H50 | H1000 H1000 H1000 | 580 | ASSEMBLY ASSEMBLY ASSEMBLY | | 77 174 |
| | X30224 Y30224 | CONE CUP | | 41024 41024 | 1 | 2GA 1EA | 91850 | 41024 | 580 | ASSEMBLY | | 72 362 |
| 30302 | X30302 Y30302 | CONE CUP | | H1000 H1000 | 1 | 2AA 1AA | 90H50 91H50 92H50 | H1000 H1000 H1000 | 580 | ASSEMBLY ASSEMBLY ASSEMBLY | | 77 174 86 220 90 071 |
| | X30302 Y30302 | CONE CUP | | H1301 H1301 | 1 | 2AA 1AA | 91H01 | H1301 | 580 | ASSEMBLY | | |
| | X30302 Y30302 | CONE CUP | | KF000 KF000 | 1 | 2AA 1AA | 92KA1 | K2000 | 580 | ASSEMBLY | | |
| | X30302 Y30302 | CONE CUP | | 41024 41024 | 1 | 2AA 1AA | 91850 | 41024 | 580 | ASSEMBLY | | 72 362 |
| 30303 | X30303 Y30303 | CONE CUP | | D1000 D1000 | 1 | 2AF 1AF | 91D50 | D1000 | 580 | ASSEMBLY | | |
| | X30303 Y30303 | CONE CUP | | H1000 H1000 | 1 | 2AA 1AA | 92H50 91H50 90H50 | H1000 H1000 H1000 | 580 | ASSEMBLY ASSEMBLY ASSEMBLY | | 90 030 86 220 77 174 |
| | X30303 Y30303 | CONE CUP | | KF000 KF000 | 1 | 2AA 1AA | 92KA1 | K2000 | 580 | ASSEMBLY | | |
| | X30303 Y30303 | CONE CUP | | 41024 41024 | 1 | 2AA 1AA | 91850 | 41024 | 580 | ASSEMBLY | | 72 362 |
| 30304 | X30304 Y30304 | CONE CUP | | E1000 E1000 | 1 | 2AF 1AF | 91E50 | E1000 | 580 | ASSEMBLY | | |
| | X30304 Y30304 | CONE CUP | | H1000 H1000 | 1 | 2AA 1AA | 91H50 90H50 | H1000 H1000 | 580 | ASSEMBLY ASSEMBLY | | 86 220 77 174 |
| | X30304 Y30304 | CONE CUP | | H2000 H2000 | 1 | 2AA 1AA | 92H50 | H2000 | 580 | ASSEMBLY | | 90 296 |
| | X30304 Y30304 | CONE CUP | | KF000 KF000 | 1 | 2AA 1AA | 9UKA1 | KU000 | 580 | ASSEMBLY | | |
| | X30304 Y30304 | CONE CUP | | KF000 KF000 | 1 | 2AA 1AA | 92KA1 | K2000 | 580 | ASSEMBLY | | |

| ASSEMBLY PART NUMBER | COMPONENT PART NUMBER | DESC | SP TY | COMP INSP | Q/A | COMP SGC | ASSY CODE | ASSY INSP | SGC | ASSY DESC | END PLAY OR PRELOAD | OBSELETE DATE | |
|-------------------------|--------------------------|------|----------|--------------|-----|-------------|--------------|--------------|-------|--------------|------------------------|------------------|--------|
| 30305 | X30304 | CONE | | 41024 | 1 | 2AA | 91850 | 41024 | 580 | ASSEMBLY | | 72 362 | |
| | Y30304 | CUP | | 41024 | 1 | 1AA | | | | | | | |
| | X30305 | CONE | | CF000 | 1 | 2AF | 92CA1 | CF000 | 580 | ASSEMBLY | | 91 022 | |
| | Y30305 | CUP | | CF000 | 1 | 1AF | | | | | | | |
| | X30305 | CONE | | D1000 | 1 | 2AF | 91D50 | D1000 | 580 | ASSEMBLY | | | |
| | Y30305 | CUP | | D1000 | 1 | 1AF | | | | | | | |
| | X30305 | CONE | | E1000 | 1 | 2AF | 91E50 | E1000 | 580 | ASSEMBLY | | | |
| | Y30305 | CUP | | E1000 | 1 | 1AF | | | | | | | |
| | X30305 | CONE | | H1000 | 1 | 2AA | 92H50 | H1000 | 580 | ASSEMBLY | | 90 213 | |
| | Y30305 | CUP | | H1000 | 1 | 1AA | 91H50 | H1000 | 580 | ASSEMBLY | | 86 220 | |
| | | | | | | | 90H50 | H1000 | 580 | ASSEMBLY | | 77 174 | |
| 30306 | X30305 | CONE | | KF000 | 1 | 2AA | 92KA1 | K2000 | 580 | ASSEMBLY | | | |
| | Y30305 | CUP | | KF000 | 1 | 1AA | | | | | | | |
| | X30305 | CONE | | K0227 | 1 | 2AA | 90KA3 | K0227 | 580 | ASSEMBLY | | | |
| | Y30305 | CUP | | K0227 | 1 | 1AA | | | | | | | |
| | X30305 | CONE | | V1000 | 1 | 2AF | 91V50 | V1000 | 580 | ASSEMBLY | | | |
| | Y30305 | CUP | | V1000 | 1 | 1AF | | | | | | | |
| | X30305 | CONE | | 41024 | 1 | 2AA | 91850 | 41024 | 580 | ASSEMBLY | | 72 362 | |
| | Y30305 | CUP | | 41024 | 1 | 1AA | | | | | | | |
| | X30306 | CONE | | BF000 | 1 | 2AF | 92BA1 | BF000 | 580 | ASSEMBLY | | | |
| | Y30306 | CUP | | BF000 | 1 | 1AF | | | | | | | |
| 30307 | X30306 | CONE | | CF000 | 1 | 2AF | 92CA2 | CF000 | 580 | ASSEMBLY | | 91 022 | |
| | Y30306 | CUP | | CF000 | 1 | 1AF | | | | | | | |
| | X30306 | CONE | | D1000 | 1 | 2AF | 91D50 | D1000 | 580 | ASSEMBLY | | | |
| | Y30306 | CUP | | D1000 | 1 | 1AF | | | | | | | |
| | X30306 | CONE | | E1000 | 1 | 2AF | 91E50 | E1000 | 580 | ASSEMBLY | | | |
| | Y30306 | CUP | | E1000 | 1 | 1AF | | | | | | | |
| | X30306 | CONE | | H1000 | 1 | 2AA | 90H50 | H1000 | 580 | ASSEMBLY | | 77 174 | |
| | Y30306 | CUP | | H1000 | 1 | 1AA | 92H50 | H1000 | 580 | ASSEMBLY | | 90 030 | |
| | | | | | | | | 91H50 | H1000 | 580 | ASSEMBLY | | 86 220 |
| | X30306 | CONE | | KF000 | 1 | 2AA | 92KA1 | K2000 | 580 | ASSEMBLY | | | |
| Y30306 | CUP | | KF000 | 1 | 1AA | | | | | | | | |
| 30307 | X30306 | CONE | | 41024 | 1 | 2AA | 91850 | 41024 | 580 | ASSEMBLY | | 72 362 | |
| | Y30306 | CUP | | 41024 | 1 | 1AA | | | | | | | |
| | X30307 | CONE | | D1000 | 1 | 2AF | 91D50 | D1000 | 580 | ASSEMBLY | | | |
| | Y30307 | CUP | | D1000 | 1 | 1BF | | | | | | | |
| | X30307 | CONE | | E1000 | 1 | 2AF | 91E50 | E1000 | 580 | ASSEMBLY | | | |
| | Y30307 | CUP | | E1000 | 1 | 1BF | | | | | | | |
| | X30307 | CONE | | H1000 | 1 | 2AA | 90H50 | H1000 | 580 | ASSEMBLY | | 77 174 | |
| | Y30307 | CUP | | H1000 | 1 | 1BA | 91H50 | H1000 | 580 | ASSEMBLY | | 86 223 | |
| | | | | | | | | 92H50 | H1000 | 580 | ASSEMBLY | | 90 030 |
| | X30307 | CONE | | H1301 | 1 | 2AA | 91H01 | H1301 | 580 | ASSEMBLY | | | |
| Y30307 | CUP | | H1301 | 1 | 1BA | | | | | | | | |
| 30307 | X30307 | CONE | | KF000 | 1 | 2AA | 92KA1 | K2000 | 580 | ASSEMBLY | | | |
| | Y30307 | CUP | | KF000 | 1 | 1BA | | | | | | | |
| | X30307 | CONE | | KF000 | 1 | 2AA | 92KA9 | K2702 | 580 | ASSEMBLY | | | |
| | Y30307 | CUP | | KF000 | 1 | 1BA | | | | | | | |
| | X30307 | CONE | | 41024 | 1 | 2AA | 91850 | 41024 | 580 | ASSEMBLY | | 72 362 | |
| | Y30307 | CUP | | 41000 | 1 | 1BA | | | | | | | |

| ASSEMBLY PART NUMBER | COMPONENT PART NUMBER | DESC | SP TY | COMP INSP | Q/A | COMP SGC | ASSY CODE | ASSY INSP | SGC | ASSY DESC | END PLAY OR PRELOAD | OBSOLETE DATE |
|-------------------------|--------------------------|-------------|-------------|--------------|-------|-------------|--------------|--------------|----------|--------------|------------------------|------------------|
| 30308 | X30308 | CONE CUP | | D1000 | 1 | 2AF | 91D50 | D1000 | 580 | ASSEMBLY | | |
| | Y30308 | | | D1000 | 1 | 1BF | | | | | | |
| | X30308 | CONE CUP | | E1000 | 1 | 2AF | 91E50 | E1000 | 580 | ASSEMBLY | | |
| | Y30308 | | | E1000 | 1 | 1BF | | | | | | |
| | X30308 | CONE CUP | | H1000 | 1 | 2AA | 90H50 | H1000 | 580 | ASSEMBLY | | 77 174 |
| | Y30308 | | | H1000 | 1 | 1BA | 91H50 | H1000 | 580 | ASSEMBLY | | 86 223 |
| | | | | | H1000 | 1 | 1BA | 92H50 | H1000 | 580 | ASSEMBLY | |
| | X30308 | CONE CUP | | KF000 | 1 | 2AA | 92KA1 | K2000 | 580 | ASSEMBLY | | |
| | Y30308 | | | KF000 | 1 | 1BA | | | | | | |
| | X30308 | CONE CUP | | K0000 | 1 | 2AA | 90KA1 | K0000 | 580 | ASSEMBLY | | |
| | Y30308 | | | K0000 | 1 | 1BA | | | | | | |
| | X30308 | CONE CUP | | 41024 | 1 | 2AA | 91850 | 41024 | 580 | ASSEMBLY | | 72 362 |
| Y30308 | 41024 | | | 1 | 1BA | | | | | | | |
| 30309 | X30309 | CONE CUP | | CF000 | 1 | 2BF | 9FCA1 | CF000 | 580 | ASSEMBLY | | |
| | Y30309 | | | CF000 | 1 | 1BF | | | | | | |
| | X30309 | CONE CUP | | D1000 | 1 | 2BF | 91D50 | D1000 | 580 | ASSEMBLY | | |
| | Y30309 | | | D1000 | 1 | 1BF | | | | | | |
| | X30309 | CONE CUP | | E1000 | 1 | 2BF | 91E50 | E1000 | 580 | ASSEMBLY | | |
| | Y30309 | | | E1000 | 1 | 1BF | | | | | | |
| | | | | | H1000 | 1 | 2BA | 92H50 | H1000 | 580 | ASSEMBLY | |
| | Y30309 | H1000 | 1 | 1BA | 91H50 | H1000 | 580 | ASSEMBLY | | 86 223 | | |
| | | | H1000 | 1 | 1BA | 90H50 | H1000 | 580 | ASSEMBLY | | 77 174 | |
| | X30309 | CONE CUP | | KF000 | 1 | 2BA | 92KA1 | K2000 | 580 | ASSEMBLY | | |
| | Y30309 | | | KF000 | 1 | 1BA | | | | | | |
| | X30309 | CONE CUP | | KF000 | 1 | 2BA | 92KA9 | K2702 | 580 | ASSEMBLY | | |
| Y30309 | KF000 | | | 1 | 1BA | | | | | | | |
| X30309 | CONE CUP | | NF000 | 1 | 2BA | 92NA3 | N2000 | 580 | ASSEMBLY | | | |
| Y30309 | | | NF000 | 1 | 1BA | | | | | | | |
| X30309 | CONE CUP | | V1000 | 1 | 2BF | 91V50 | V1000 | 580 | ASSEMBLY | | | |
| Y30309 | | | V1000 | 1 | 1BF | | | | | | | |
| X30309 | CONE CUP | | 41024 | 1 | 2BA | 91850 | 41024 | 580 | ASSEMBLY | | 72 362 | |
| Y30309 | | | 41024 | 1 | 1BA | | | | | | | |
| 30310 | X30310 | CONE CUP | | D1000 | 1 | 2BF | 91D50 | D1000 | 580 | ASSEMBLY | | |
| | Y30310 | | | D1000 | 1 | 1BF | | | | | | |
| | X30310 | CONE CUP | | H1000 | 1 | 2BA | 91H50 | H1000 | 580 | ASSEMBLY | | 86 223 |
| | Y30310 | | | H1000 | 1 | 1BA | 90H50 | H1000 | 580 | ASSEMBLY | | 77 174 |
| | | | | | H1000 | 1 | 1BA | 92H50 | H1000 | 580 | ASSEMBLY | |
| | X30310 | CONE CUP | | KF000 | 1 | 2BA | 92KA1 | K2000 | 580 | ASSEMBLY | | |
| | Y30310 | | | KF000 | 1 | 1BA | | | | | | |
| | X30310 | CONE CUP | | NF000 | 1 | 2BA | 92NA2 | N2000 | 580 | ASSEMBLY | | |
| | Y30310 | | | NF000 | 1 | 1BA | | | | | | |
| | X30310 | CONE CUP | | 41024 | 1 | 2BA | 91850 | 41024 | 580 | ASSEMBLY | | 72 362 |
| | Y30310 | | | 41024 | 1 | 1BA | | | | | | |
| | 30311 | X30311 | CONE CUP | | H1000 | 1 | 2BA | 92H50 | H1000 | 580 | ASSEMBLY | |
| Y30311 | | H1000 | | | 1 | 1CA | 90H50 | H1000 | 580 | ASSEMBLY | | 77 174 |
| | | | | | H1000 | 1 | 1CA | 91H50 | H1000 | 580 | ASSEMBLY | |
| X30311 | | CONE CUP | | KF000 | 1 | 2BA | 92KA1 | K2000 | 580 | ASSEMBLY | | |
| Y30311 | | | KF000 | 1 | 1CA | | | | | | | |

| ASSEMBLY PART NUMBER | COMPONENT PART NUMBER | DESC | SP TY | COMP INSP | Q/A | COMP SGC | ASSY CODE | ASSY INSP | SGC | ASSY DESC | END PLAY OR PRELOAD | OBSOLETE DATE |
|-------------------------|--------------------------|------|----------|--------------|-------|-------------|--------------|--------------|----------|--------------|------------------------|------------------|
| 30312 | X30311 | CONE | | 41024 | | 1 2BA | 91850 | 41024 | 580 | ASSEMBLY | | 72 362 |
| | Y30311 | CUP | | 41024 | | 1 1CA | | | | | | |
| | X30312 | CONE | | D1000 | | 1 2CF | 91D50 | D1000 | 580 | ASSEMBLY | | |
| | Y30312 | CUP | | D1000 | | 1 1CF | | | | | | |
| | X30312 | CONE | | E1000 | | 1 2CF | 91E50 | E1000 | 580 | ASSEMBLY | | |
| | Y30312 | CUP | | E1000 | | 1 1CF | | | | | | |
| | X30312 | CONE | | E2000 | | 1 2CF | 92E50 | E2000 | 580 | ASSEMBLY | | |
| | Y30312 | CUP | | E2000 | | 1 1CF | | | | | | |
| | X30312 | CONE | | H1000 | | 1 2CA | 91H50 | H1000 | 580 | ASSEMBLY | | 86 223 |
| | Y30312 | CUP | | H1000 | | 1 1CA | 92H50 | H1000 | 580 | ASSEMBLY | | 89 228 |
| | | | | | | | 90H50 | H1000 | 580 | ASSEMBLY | | 77 174 |
| | X30312 | CONE | | KF000 | | 1 2CA | 90KA1 | KU000 | 580 | ASSEMBLY | | |
| Y30312 | CUP | | KF000 | | 1 1CA | | | | | | | |
| X30312 | CONE | | KF000 | | 1 2CA | 92KA1 | K2000 | 580 | ASSEMBLY | | | |
| Y30312 | CUP | | KF000 | | 1 1CA | | | | | | | |
| X30312 | CONE | | KF000 | | 1 2CA | 92KA9 | K2702 | 580 | ASSEMBLY | | | |
| Y30312 | CUP | | KF000 | | 1 1CA | | | | | | | |
| X30312 | CONE | | NF000 | | 1 2CA | 92NA2 | N2000 | 580 | ASSEMBLY | | | |
| Y30312 | CUP | | NF000 | | 1 1CA | | | | | | | |
| X30312 | CONE | | V1000 | | 1 2CF | 91V50 | V1000 | 580 | ASSEMBLY | | | |
| Y30312 | CUP | | V1000 | | 1 1CF | | | | | | | |
| X30312 | CONE | | 41024 | | 1 2CA | 91850 | 41024 | 580 | ASSEMBLY | | 72 362 | |
| Y30312 | CUP | | 41024 | | 1 1CA | | | | | | | |
| 30313 | X30313 | CONE | | D1000 | | 1 2CF | 91D50 | D1000 | 580 | ASSEMBLY | | |
| | Y30313 | CUP | | D1000 | | 1 1CF | | | | | | |
| | X30313 | CONE | | E1000 | | 1 2CF | 91E50 | E1000 | 580 | ASSEMBLY | | |
| | Y30313 | CUP | | E1000 | | 1 1CF | | | | | | |
| | X30313 | CONE | | H1000 | | 1 2CA | 90H50 | H1000 | 580 | ASSEMBLY | | 77 174 |
| | Y30313 | CUP | | H1000 | | 1 1CA | 92H50 | H1000 | 580 | ASSEMBLY | | 89 228 |
| | | | | | | | 91H50 | H1000 | 580 | ASSEMBLY | | 86 223 |
| | X30313 | CONE | | KF000 | | 1 2CA | 92KA1 | K2000 | 580 | ASSEMBLY | | |
| | Y30313 | CUP | | KF000 | | 1 1CA | | | | | | |
| | X30313 | CONE | | NF000 | | 1 2CA | 92NA2 | N2000 | 580 | ASSEMBLY | | |
| | Y30313 | CUP | | NF516 | | 1 1CA | | | | | | |
| | X30313 | CONE | | 41024 | | 1 2CA | 91850 | 41024 | 580 | ASSEMBLY | | 72 362 |
| Y30313 | CUP | | 41024 | | 1 1CA | | | | | | | |
| 30314 | X30314 | CONE | | H1000 | | 1 2CA | 91H50 | H1000 | 580 | ASSEMBLY | | 86 223 |
| | Y30314 | CUP | | H1000 | | 1 1CA | 92H50 | H1000 | 580 | ASSEMBLY | | 92 017 |
| | | | | | | | 90H50 | H1000 | 580 | ASSEMBLY | | 77 174 |
| X30314 | CONE | | KF000 | | 1 2CA | 92KA1 | K2000 | 580 | ASSEMBLY | | | |
| Y30314 | CUP | | KF000 | | 1 1CA | | | | | | | |
| X30314 | CONE | | 41024 | | 1 2CA | 91850 | 41024 | 580 | ASSEMBLY | | 72 362 | |
| Y30314 | CUP | | 41024 | | 1 1CA | | | | | | | |
| 30315 | X30315 | CONE | | H0000 | | 1 2DA | 90H50 | H0000 | 580 | ASSEMBLY | | |
| | Y30315 | CUP | | H0000 | | 1 1CA | | | | | | |
| | X30315 | CONE | | H1000 | | 1 2DA | 91H50 | H0000 | 580 | ASSEMBLY | | 73 082 |
| Y30315 | CUP | | H1000 | | 1 1CA | | | | | | | |
| X30315 | CONE | | H2000 | | 1 2DA | 92H50 | H0000 | 580 | ASSEMBLY | | | |
| Y30315 | CUP | | H2000 | | 1 1CA | | | | | | | |

| ASSEMBLY PART NUMBER | COMPONENT PART NUMBER | DESC | SP TY | COMP INSP | Q/A | COMP SGC | ASSY CODE | ASSY INSP | SGC | ASSY DESC | END PLAY OR PRELOAD | OR | OBSOLETE DATE |
|----------------------|-----------------------|-----------|-------|-----------|-----|----------|-----------|-----------|-----|-----------|---------------------|----|---------------|
| | X30315 | CONE | | K0025 | 1 | 2DA | 90KA1 | K0025 | 5CA | ASSEMBLY | | | |
| | Y30315 | CUP | | K0000 | 1 | 1CA | | | | | | | |
| | X30315 | CONE | | 41000 | 1 | 2DA | 91850 | 41024 | 580 | ASSEMBLY | | | 72 362 |
| | Y30315 | CUP | | 41024 | 1 | 1CA | | | | | | | |
| 30316 | X30316 | CONE | | H1000 | 1 | 2EA | 92H50 | H1000 | 580 | ASSEMBLY | | | |
| | Y30316 | CUP | | H1000 | 1 | 1DA | 91H50 | H1000 | 580 | ASSEMBLY | | | 77 174 |
| | | | | | | | 90H50 | H1000 | 580 | ASSEMBLY | | | |
| | X30316 | CONE | | KF000 | 1 | 2EA | 92KA1 | KF000 | 580 | ASSEMBLY | | | |
| | Y30316 | CUP | | KF000 | 1 | 1DA | | | | | | | |
| | X30316 | CONE | | 41024 | 1 | 2EA | 91850 | 41024 | 580 | ASSEMBLY | | | 72 362 |
| | Y30316 | CUP | | 41024 | 1 | 1DA | | | | | | | |
| 30317 | X30317 | CONE | | H1000 | 1 | 2FA | 91H50 | H0000 | 580 | ASSEMBLY | | | |
| | Y30317 | CUP | | H1000 | 1 | 1CA | | | | | | | |
| | X30317 | CONE | | H1000 | 1 | 2FA | 90H50 | H1000 | 580 | ASSEMBLY | | | 77 174 |
| | Y30317 | CUP | | H1000 | 1 | 1CA | | | | | | | |
| 30318 | X30318 | CONE | | H1000 | 1 | 2FA | 92H50 | H1000 | 580 | ASSEMBLY | | | |
| | Y30318 | CUP | | H1000 | 1 | 1DA | 91H50 | H1000 | 580 | ASSEMBLY | | | 86 223 |
| | | | | | | | 90H50 | H1000 | 580 | ASSEMBLY | | | 77 174 |
| | X30318 | CONE | | KF000 | 1 | 2FA | 92KA1 | KF000 | 580 | ASSEMBLY | | | |
| | Y30318 | CUP | | KF000 | 1 | 1DA | | | | | | | |
| | X30318 | CONE | | 41024 | 1 | 2FA | 91850 | 41024 | 580 | ASSEMBLY | | | 72 362 |
| | Y30318 | CUP | | 41024 | 1 | 1DA | | | | | | | |
| K30563 | K30563 | HOUSING | | | 1 | 487 | 90010 | | 486 | HSG ASSY | | | 84 207 |
| | K30564 | WEARPLATE | | | 1 | 489 | | | | | | | |
| | T56882 | HSG LINER | | | 2 | 489 | | | | | | | |
| | T57878 | LINER | | | 2 | 489 | | | | | | | |
| | T60539 | LUG LINER | | | 2 | 489 | | | | | | | |
| K30575 | K30575 | HOUSING | | | 1 | 487 | 90010 | | 486 | HSG ASSY | | | 84 207 |
| | T64509 | WEARPLATE | | | 1 | 489 | | | | | | | |
| | T64510 | WEARPLATE | | | 2 | 489 | | | | | | | |
| | T68320A | STUD | | | 2 | 469 | | | | | | | |
| | T69419 | LUG LINER | | | 2 | 489 | | | | | | | |
| K30581 | K30581 | AEC | | | 1 | 480 | 90010 | | 488 | AEC ASSY | | | |
| | T59841C | IMPELLER | | | 1 | 474 | | | | | | | |
| T30620 | XC2096-B | ROLLER | | | 90 | 010 | 90012 | 30000 | 377 | ASSEMBLY | | | |
| | T30620 | RACE | | 30000 | 1 | 077 | 93000 | 30000 | 377 | ASSEMBLY | | | 79 352 |
| | T30620C | CAGE RING | | | 1 | 061 | | | | | | | |
| | T30620F | RACE | | 30000 | 1 | 077 | | | | | | | |
| | XC2096-B | ROLLER | | | 90 | 010 | 90013 | 30038 | 377 | ASSEMBLY | | | |
| | T30620 | RACE | | 30038 | 1 | 077 | | | | | | | |
| | T30620C | CAGE RING | | | 1 | 061 | | | | | | | |
| | T30620F | RACE | | 30038 | 1 | 077 | | | | | | | |
| 31305 | X31305 | CONE | | E1000 | 1 | 2AF | 91E50 | E1000 | 580 | ASSEMBLY | | | |
| | Y31305 | CUP | | E1000 | 1 | 1AF | | | | | | | |
| | X31305 | CONE | | H1000 | 1 | 2AA | 90H50 | H1000 | 580 | ASSEMBLY | | | 77 174 |
| | Y31305 | CUP | | H1000 | 1 | 1AA | 91H50 | H1000 | 580 | ASSEMBLY | | | 74 087 |
| | X31305 | CONE | | 41024 | 1 | 2AA | 91850 | 41024 | 580 | ASSEMBLY | | | 72 362 |
| | Y31305 | CUP | | 41024 | 1 | 1AA | | | | | | | |
| | X31305 | CONE | | H1000 | 2 | 2AA | 91H01 | H1000 | 580 | ASSEMBLY | EP .0200 | | 74 087 |
| | Y31305 | CUP | | H1000 | 2 | 1AA | | | | | | | |
| | X15-31305 | CONE SPCR | | 20000 | 1 | 04A | | | | | | | |

| ASSEMBLY PART NUMBER | COMPONENT PART NUMBER | DESC | SP TY | COMP INSP | Q/A | COMP SGC | ASSY CODE | ASSY INSP | SGC | ASSY DESC | END PLAY OR PRELOAD | OBSOLETE DATE |
|-------------------------|--------------------------|------|----------|--------------|-----|-------------|--------------|--------------|-----|--------------|------------------------|------------------|
| 31306 | X31306 | CONE | | D1000 | 1 | 2AF | 91D50 | D1000 | 580 | ASSEMBLY | | 73 291 |
| | Y31306 | CUP | | D1000 | 1 | 1AF | | | | | | |
| | X31306 | CONE | | E1000 | 1 | 2AF | 91E50 | E1000 | 580 | ASSEMBLY | | 73 291 |
| | Y31306 | CUP | | E1000 | 1 | 1AF | | | | | | |
| 31306 | X31306 | CONE | | H1000 | 1 | 2AA | 90H50 | H1000 | 580 | ASSEMBLY | | 77 174 |
| | Y31306 | CUP | | H1000 | 1 | 1AA | 91H50 | H1000 | 580 | ASSEMBLY | | 73 291 |
| | X31306 | CONE | | 41024 | 1 | 2AA | 91850 | 41024 | 580 | ASSEMBLY | | 72 362 |
| | Y31306 | CUP | | 41024 | 1 | 1AA | | | | | | |
| 31307 | X31307 | CONE | | E1000 | 1 | 2AF | 91E50 | E1000 | 580 | ASSEMBLY | | 87 307 |
| | Y31307 | CUP | | E1000 | 1 | 1BF | | | | | | |
| | X31307 | CONE | | H1000 | 1 | 2AA | 91H50 | H1000 | 580 | ASSEMBLY | | 87 307 |
| | Y31307 | CUP | | H1000 | 1 | 1BA | 92H50 | H1000 | 580 | ASSEMBLY | | 77 174 |
| 31308 | X31308 | CONE | | 41024 | 1 | 2AA | 91850 | 41024 | 580 | ASSEMBLY | | 72 362 |
| | Y31308 | CUP | | 41024 | 1 | 1BA | | | | | | |
| | X31308 | CONE | | BE000 | 1 | 2BF | 9EBA4 | BE000 | 580 | ASSEMBLY | | |
| | Y31308 | CUP | | BE000 | 1 | 1BF | | | | | | |
| 31308 | X31308 | CONE | | CF000 | 1 | 2BF | 92CA3 | CF000 | 580 | ASSEMBLY | | |
| | Y31308 | CUP | | CF000 | 1 | 1BF | | | | | | |
| | X31308 | CONE | | E1000 | 1 | 2BF | 91E50 | E1000 | 580 | ASSEMBLY | | |
| | Y31308 | CUP | | E1000 | 1 | 1BF | | | | | | |
| 31308 | X31308 | CONE | | HF163 | 1 | 2BA | 9FHA1 | HF534 | 580 | ASSEMBLY | | 86 027 |
| | Y31308 | CUP | | HF000 | 1 | 1BA | | | | | | |
| | X31308 | CONE | | H1000 | 1 | 2BA | 9UH50 | HU000 | 580 | ASSEMBLY | | 90 207 |
| | Y31308 | CUP | | H1000 | 1 | 1BA | | | | | | |
| 31308 | X31308 | CONE | | H1000 | 1 | 2BA | 92H50 | H1000 | 580 | ASSEMBLY | | 90 213 |
| | Y31308 | CUP | | H1000 | 1 | 1BA | 91H50 | H1000 | 580 | ASSEMBLY | | 77 174 |
| | X31308 | CONE | | H1000 | 1 | 2AA | 92H53 | H1534 | 580 | ASSEMBLY | | |
| | Y31308 | CUP | | H1000 | 1 | 1BA | 92HA2 | H1534 | 580 | ASSEMBLY | | |
| 31308 | X31308 | CONE | | H1024 | 1 | 2BA | 92H52 | H1488 | 580 | ASSEMBLY | | 91 249 |
| | Y31308 | CUP | | H1024 | 1 | 1BA | | | | | | |
| | X31308 | CONE | | H1516 | 1 | 2BA | 92H54 | H1516 | 580 | ASSEMBLY | | |
| | Y31308 | CUP | | H1516 | 1 | 1BA | | | | | | |
| 31308 | X31308 | CONE | | KF000 | 1 | 2BA | 92KA1 | KF000 | 580 | ASSEMBLY | | |
| | Y31308 | CUP | | KF000 | 1 | 1BA | | | | | | |
| | X31308 | CONE | | KF000 | 1 | 2BA | 92KA4 | KF488 | 580 | ASSEMBLY | | |
| | Y31308 | CUP | | KF000 | 1 | 1BA | | | | | | |
| 31308 | X31308 | CONE | | KF000 | 1 | 2BA | 9UKA1 | KU000 | 580 | ASSEMBLY | | |
| | Y31308 | CUP | | KF000 | 1 | 1BA | | | | | | |
| | X31308 | CONE | | KF000 | 1 | 2BA | 92KA5 | K2534 | 580 | ASSEMBLY | | |
| | Y31308 | CUP | | KF000 | 1 | 1BA | | | | | | |
| 31308 | X31308 | CONE | | 41024 | 1 | 2BA | 91850 | 41024 | 580 | ASSEMBLY | | 72 362 |
| | Y31308 | CUP | | 41024 | 1 | 1BA | | | | | | |
| | X31308 | CONE | | H1024 | 2 | 2BA | 92H51 | H1488 | 580 | ASSEMBLY | EP .0040 | |
| | Y31308 | CUP | | H1024 | 2 | 1BA | | | | | | |
| Y15-31308 | CUP SPCR | S | 20000 | 1 | 04B | | | | | | | |

| ASSEMBLY PART NUMBER | COMPONENT PART NUMBER | DESC | SP TY | COMP INSP | Q/A | COMP SGC | ASSY CODE | ASSY INSP | SGC | ASSY DESC | END PLAY OR PRELOAD | OBsolete DATE |
|-------------------------|-------------------------------|---------------------|----------|-------------------------|-----|-------------------|-------------------------|-------------------------|-------------------|----------------------------------|------------------------|----------------------------|
| | X31308 Y31308 Y15-31308 | CONE CUP SPCR | S | KF000 KF000 2F000 | 2 | 2BA 1BA 04B | 92KA6 | K2000 | 580 | ASSEMBLY | EP .0040 | |
| 31308V | X31308V Y31308V | CONE CUP | | KF000 KF000 | 1 | 2BA 1BA | 92KA1 | KF000 | 580 | ASSEMBLY | | |
| 31309 | X31309 Y31309 | CONE CUP | | E1000 E1000 | 1 | 2BF 1BF | 91E50 | E1000 | 580 | ASSEMBLY | | 76 176 |
| | X31309 Y31309 | CONE CUP | | H1000 H1000 | 1 | 2BA 1BA | 91H50 92H50 90H50 | H1000 H1000 H1000 | 580 580 580 | ASSEMBLY ASSEMBLY ASSEMBLY | | 76 176 76 176 77 174 |
| | X31309 Y31309 | CONE CUP | | 41024 41024 | 1 | 2BA 1BA | 91850 | 41024 | 580 | ASSEMBLY | | 72 362 |
| 31310 | X31310 Y31310 | CONE CUP | | E1000 E1000 | 1 | 2BF 1BF | 91E50 | E1000 | 580 | ASSEMBLY | | 75 308 |
| | X31310 Y31310 | CONE CUP | | H1000 H1000 | 1 | 2BA 1BA | 91H50 90H50 | H1000 H1000 | 580 580 | ASSEMBLY ASSEMBLY | | 75 308 77 174 |
| | X31310 Y31310 | CONE CUP | | 41024 41024 | 1 | 2BA 1BA | 91850 | 41024 | 580 | ASSEMBLY | | 72 362 |
| 31311 | X31311 Y31311 | CONE CUP | | H1000 H1000 | 1 | 2BA 1CA | 91H50 | H0000 | 580 | ASSEMBLY | | 74 063 |
| | X31311 Y31311 | CONE CUP | | H1000 H1000 | 1 | 2BA 1CA | 90H50 | H1000 | 580 | ASSEMBLY | | 77 174 |
| | X31311 Y31311 | CONE CUP | | V1000 V1000 | 1 | 2BA 1CF | 91V50 | V1000 | 580 | ASSEMBLY | | 74 063 |
| | X31311 Y31311 | CONE CUP | | 41024 41024 | 1 | 2BA 1CA | 91850 | 41024 | 580 | ASSEMBLY | | 72 362 |
| 31312 | X31312 Y31312 | CONE CUP | | H1000 H1000 | 1 | 2BA 1CA | 91H50 90H50 | H1000 H1000 | 580 580 | ASSEMBLY ASSEMBLY | | 73 250 77 174 |
| | X31312 Y31312 | CONE CUP | | 41024 41024 | 1 | 2BA 1CA | 91850 | 41024 | 580 | ASSEMBLY | | 72 362 |
| 31312-BNA | 31312-BNA 31312AXD | CONE CUP | | H1000 H1000 | 1 | 2CA 1CB | 92H50 | H1000 | 580 | ASSEMBLY | | |
| | 31312-BNA 31312AXD | CONE CUP | | H1000 H1000 | 2 | 2CA 1CB | 91H50 | H1000 | 580 | ASSEMBLY | | |
| 31313 | X31313 Y31313 | CONE CUP | | H1000 H1000 | 1 | 2CA 1CA | 91H50 | H0000 | 580 | ASSEMBLY | | 84 100 |
| | X31313 Y31313 | CONE CUP | | H1000 H1000 | 1 | 2CA 1CA | 90H50 92H50 | H1000 H1000 | 580 580 | ASSEMBLY ASSEMBLY | | 77 174 |
| | X31313 Y31313 | CONE CUP | | V1000 V1000 | 1 | 2CF 1CF | 91V50 | V1000 | 580 | ASSEMBLY | | |
| | X31313 Y31313 | CONE CUP | | 41024 41024 | 1 | 2CA 1CA | 91850 | 41024 | 580 | ASSEMBLY | | 72 362 |
| 31314 | X31314 Y31314 | CONE CUP | | H1000 H1000 | 1 | 2CA 1CA | 91H50 | H0000 | 580 | ASSEMBLY | | 75 150 |
| | X31314 Y31314 | CONE CUP | | H1000 H1000 | 1 | 2CA 1CA | 90H50 | H1000 | 580 | ASSEMBLY | | 77 174 |
| | X31314 Y31314 | CONE CUP | | 41024 41024 | 1 | 2CA 1CA | 91850 | 41024 | 580 | ASSEMBLY | | 72 362 |

| ASSEMBLY PART NUMBER | COMPONENT PART NUMBER | DESC | SP TY | COMP INSP | Q/A | COMP SGC | ASSY CODE | ASSY INSP | SGC | ASSY DESC | END PLAY OR PRELOAD | DR | OBSOLETE DATE |
|-------------------------|--------------------------|-----------|----------|--------------|-----|-------------|--------------|--------------|-----|--------------|------------------------|----|------------------|
| 31316 | X31316 | CONE | | H1000 | | 1 2DA | 91H50 | H0000 | 580 | ASSEMBLY | | | 75 148 |
| | Y31316 | CUP | | H1000 | | 1 1DA | | | | | | | |
| | X31316 | CONE | | H1000 | | 1 2DA | 90H50 | H1000 | 580 | ASSEMBLY | | | 77 174 |
| | Y31316 | CUP | | H1000 | | 1 1DA | | | | | | | |
| 31316 | X31316 | CONE | | 41024 | | 1 2DA | 91850 | 41024 | 580 | ASSEMBLY | | | 72 362 |
| | Y31316 | CUP | | 41024 | | 1 1DA | | | | | | | |
| | | | | | | | | | | | | | |
| LM31331 | LH31331 | CONE | | 40000 | | 1 2AB | 90010 | 40000 | 530 | ASSEMBLY | | | |
| | 1C | ROLLER | | | | 26 010 | | | | | | | |
| | T45002 | NUT | | | | 1 463 | | | | | | | |
| | T54591 | WASHER | | | | 1 469 | | | | | | | |
| | K91447 | LOOSE RIB | | 40000 | | 1 490 | | | | | | | |
| | | | | | | | | | | | | | |
| LM31331 | LH31331 | CONE | | 40000 | | 1 2AB | 90012 | 40000 | 531 | ASSEMBLY | | | |
| | 1C | ROLLER | | | | 26 010 | | | | | | | |
| | T45002 | NUT | | | | 1 463 | | | | | | | |
| | T54591 | WASHER | | | | 1 469 | | | | | | | |
| | K91447 | LOOSE RIB | | 40000 | | 1 490 | | | | | | | |
| | | | | | | | | | | | | | |
| LM31333 | LH31333 | CONE | | 40000 | | 1 2AB | 90011 | 40000 | 530 | ASSEMBLY | | | |
| | 1C | ROLLER | | | | 26 010 | | | | | | | |
| | T45002 | NUT | | | | 1 463 | | | | | | | |
| | T54591 | WASHER | | | | 1 469 | | | | | | | |
| | K91447 | LOOSE RIB | | 40000 | | 1 490 | | | | | | | |
| | | | | | | | | | | | | | |
| LM31333 | LH31333 | CONE | | 40000 | | 2 2AB | 90013 | 40000 | 531 | ASSEMBLY | | | |
| | 1C | ROLLER | | | | 52 010 | | | | | | | |
| | T45002 | NUT | | | | 1 463 | | | | | | | |
| | T54591 | WASHER | | | | 1 469 | | | | | | | |
| | K91447 | LOOSE RIB | | 40000 | | 2 490 | | | | | | | |
| | | | | | | | | | | | | | |
| 31523RB | 31523RB | CUP | | 20357 | | 1 1BA | 90020 | 20357 | 541 | ASSEMBLY | | | |
| | K53479 | SNAP RING | | | | 1 090 | | | | | | | |
| | | | | | | | | | | | | | |
| 31523RB | 31523RB | CUP | | 40355 | | 1 1BA | 90021 | 40355 | 541 | ASSEMBLY | | | |
| | K53479 | SNAP RING | | | | 1 090 | | | | | | | |
| | | | | | | | | | | | | | |
| 31523RB | 31523RB | CUP | | 40357 | | 1 1BA | 90023 | 40357 | 541 | ASSEMBLY | | | |
| | K53479 | SNAP RING | | | | 1 090 | | | | | | | |
| | | | | | | | | | | | | | |
| 31590 | 31590 | CONE | | 0 | | 1 2AF | 90016 | 0 | 6AA | ASSEMBLY | | | |
| | 31520 | CUP | | 0 | | 1 1AF | | | | | | | |
| 31590-B | 31590-B | CONE | | 00 | | 1 2AF | 90018 | 00 | 7AA | ASSEMBLY | | | 82 308 |
| | 31520 | CUP | | 00 | | 1 1AF | | | | | | | |
| 31593 | 31593 | CONE | | 0 | | 1 2AF | 90010 | 0 | 6AA | ASSEMBLY | | | |
| | 31520 | CUP | | 0 | | 1 1AF | | | | | | | |
| 31593-B | 31593-B | CONE | | 0 | | 1 2AF | 90025 | 0 | 6BA | ASSEMBLY | | | |
| | 31520-B | CUP | | 0 | | 1 1BH | | | | | | | |
| 31593-B | 31593-B | CONE | | 00 | | 1 2AF | 90019 | 00 | 7AA | ASSEMBLY | | | 82 308 |
| | 31520 | CUP | | 00 | | 1 1AF | | | | | | | |
| 31594 | 31594 | CONE | | 0 | | 1 2AF | 90011 | 0 | 6AA | ASSEMBLY | | | |
| | 31520 | CUP | | 0 | | 1 1AF | | | | | | | |
| 31594 | 31594 | CONE | | 0-30 | | 1 2AF | 90026 | 0-33 | 6AA | ASSEMBLY | | | |
| | 31520 | CUP | | 0-39 | | 1 1AF | | | | | | | |
| 31594 | 31594 | CONE | | 0 | | 1 2AF | 90022 | 0 | 6AA | ASSEMBLY | | | |
| | 31521 | CUP | | 0 | | 1 1AF | | | | | | | |
| 31597 | 31597 | CONE | | 0 | | 1 2AF | 90015 | 0 | 6AA | ASSEMBLY | | | |
| | 31520 | CUP | | 0 | | 1 1AF | | | | | | | |
| | 31597 | CONE | | 0 | | 1 2AF | 90012 | 0 | 6BA | ASSEMBLY | | | |
| | 31520-B | CUP | | 0 | | 1 1BH | | | | | | | |

| ASSEMBLY PART NUMBER | COMPONENT PART NUMBER | DESC | SP TY | COMP INSP | Q/A | COMP SGC | ASSY CODE | ASSY INSP | ASSY SGC-DESC | END PLAY OR PRELOAD | OBSOLETE DATE |
|-------------------------|----------------------------|-----------------------------------|----------|----------------|-----|-------------------------|----------------------------------|----------------------------------|--|------------------------|--------------------------------------|
| | 31597 31521 | CONE CUP | | 0 0 | | 1 2AF 1 1AF | 90013 | 0 | 6AA ASSEMBLY | | |
| 31597-B | 31597-B 31520 | CONE CUP | | 00 00 | | 1 2AF 1 1AF | 90024 | 00 | 7AA ASSEMBLY | | 82 308 |
| 131661 | 131661 131668 131669 | HOUSING WEARPLATE LUG LINER | | | | 1 487 1 489 2 489 | 90010 | | 486 HSG ASSY | | 84 207 |
| 32004X | X32004X Y32004X | CONE CUP | | KF000 KF000 | | 1 2AA 1 1AA | 92KA1 | KF000 | 580 ASSEMBLY | | |
| 32005X | X32005X Y32005X | CONE CUP | | H1000 H1000 | | 1 2AA 1 1AA | 92H50 | H1000 | 580 ASSEMBLY | | 89 228 |
| | X32005X Y32005X | CONE CUP | | KF000 KF000 | | 1 2AA 1 1AA | 92KA1 | K2000 | 580 ASSEMBLY | | |
| | X32005X Y32005X | CONE CUP | | KF000 KF000 | | 1 2AA 1 1AA | 92KA9 | K2702 | 580 ASSEMBLY | | |
| | X32005X Y32005X | CONE CUP | | NF000 NF000 | | 1 2AA 1 1AA | 92NA3 | N2000 | 580 ASSEMBLY | | |
| 32006X | X32006X Y32006X | CONE CUP | | CE000 CE000 | | 1 2AF 1 1AF | 9ECA1 | CE000 | 580 ASSEMBLY | | |
| | X32006X Y32006X | CONE CUP | | CH000 CH000 | | 1 2AF 1 1AF | 9GCA1 | CH000 | 580 ASSEMBLY | | |
| | X32006X Y32006X | CONE CUP | | E2000 E2000 | | 1 2AA 1 1AA | 92E50 | | 580 ASSEMBLY | | 90 263 |
| | X32006X Y32006X | CONE CUP | | HF000 HF000 | | 1 2AA 1 1AA | 92HA2 | HF702 | 580 ASSEMBLY | | |
| | X32006X Y32006X | CONE CUP | | H1000 H1000 | | 1 2AA 1 1AA | 91H52 90H50 91H50 92H50 | H1000 H1000 H1000 H1000 | 580 ASSEMBLY 580 ASSEMBLY 580 ASSEMBLY 580 ASSEMBLY | | 74 151 77 174 86 223 90 030 |
| | X32006X Y32006X | CONE CUP | | H1479 H1479 | | 1 2AA 1 1AA | 91H51 92H51 | H1479 H1479 | 580 ASSEMBLY 580 ASSEMBLY | | |
| | X32006X Y32006X | CONE CUP | | KF000 KF000 | | 1 2AA 1 1AA | 92KA1 | K2000 | 580 ASSEMBLY | | |
| | X32006X Y32006X | CONE CUP | | KF000 KF000 | | 1 2AA 1 1AA | 92KA9 | K2702 | 580 ASSEMBLY | | |
| | X32006X Y32006X | CONE CUP | | NF000 NF000 | | 1 2AA 1 1AA | 92NA2 | N2000 | 580 ASSEMBLY | | |
| | X32006X Y32006X | CONE CUP | | NF000 NF516 | | 1 2AA 1 1AA | 92NA6 | N2000 | 580 ASSEMBLY | | |
| | X32006X Y32006X | CONE CUP | | NF479 NF479 | | 1 2AA 1 1AA | 92NA5 | N2479 | 580 ASSEMBLY | | |
| | X32006X Y32006X | CONE CUP | | N1907 N1907 | | 1 2AA 1 1AA | 91N01 | N1907 | 580 ASSEMBLY | | |
| | X32006X Y32006X | CONE CUP | | NF000 NF000 | | 2 2AA 2 1AA | 92NA7 | N2000 | 580 ASSEMBLY | | |
| | JXH3005A JYH5505TSR | CUP SPCR CUP SPCR | A TSR | 2F000 2F000 | | 1 04A 1 04A | | | | | |
| | X32006X YGA32006X | CONE CUP | | KF000 KF000 | | 1 2AA 1 1AA | 92KA8 | K2000 | 580 ASSEMBLY | | |